

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22008489/ENY3M4**Date:** 11/10/2022**REFERENCE**

Insured/Claimant: CHING AH CHOON Policy No: SP200743851-01
Date of Loss: 16/08/2022 Nature of Claim: OD Claim No: 202222006204

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGR52Y**
Make & Model: TOYOTA VELLFIRE, 2.5 Z G-EDITION CVT (A) Engine No: 2ARH695016
Reg. Date: 14/11/2016 (Man. Year: 2016) Chassis No: AGH300055941
Colour: Black Odometer: 94454 km
Engine Capacity: 2493 cc
Market Value/New Car Price: S\$152,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,713.00	6,842.00	2,871.00	29.56
Miscellaneous Items	160.00	90.00	70.00	43.75
Labour	1,700.00	1,300.00	400.00	23.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,573.00	8,232.00	3,341.00	28.87
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	11,573.00	7,632.00	3,941.00	34.05
+ GST 7.00/7.00% (S\$)	810.11	534.24	275.87	34.05
Nett Amount (S\$)	12,383.11	8,166.24	4,216.87	34.05

INSPECTION

Date of Assignment: 31/08/2022 Present Location: Cheng Auto Bodyworks (HQ)
Date Inspected: 12/09/2022 Inspected At: Cheng Auto Bodyworks (HQ)
5 Soon Lee Street #01-62 Pioneer Point
Singapore 627607
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2022)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.5 Z G-EDITION CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGR52Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET (WCP)	Repair	550.00 F	*- F
2	1	NA	*BONNET HINGE RH (WCP)	Bent	45.00 F	*45.00 F
3	1	NA	*BONNET HINGE LH (WCP)	Bent	45.00 F	*45.00 F
4	1	NA	*BONNET ISOLATOR (WCP)	Not Necessary	140.00 F	*- F
5	1	NA	*BONNET LOCK ASSY (WCP)	Not Necessary	90.00 F	*- F
6	1	NA	*BONNET RUBBER (WCP)	Not Necessary	30.00 F	*- F
7	1	NA	*BONNET CHROME (WCP)	Cracked	250.00 F	*250.00 F
8	1	NA	*GRILLE ASSY (WCP)	Broken	700.00 F	*700.00 F
9	1	NA	*GRILLE LOGO (WCP)	Necessary	90.00 F	*90.00 F
10	1	NA	*HEADLAMP RH (WCP)	Broken	1,850.00 F	*1,850.00 F
11	1	NA	*HEADLAMP LH (WCP)	Broken	1,850.00 F	*1,850.00 F
12	1	NA	*FOGLAMP GRILLE RH WITH CHROME (WCP)	Not Necessary	180.00 F	*- F
13	1	NA	*FOGLAMP GRILLE LH WITH CHROME (WCP)	Broken	180.00 F	*180.00 F
14	1	NA	*REINFORCEMENT (WCP)	Bent	200.00 F	*200.00 F
15	1	NA	*SPONGE (WCP)	Broken	70.00 F	*70.00 F
16	1	NA	*NO PLATE GARNISH COVER (WCP)	Not Necessary	150.00 F	*- F
17	1	NA	*FRT BUMPER (WCP)	Broken	600.00 F	*600.00 F
18	1	NA	*FRT BUMPER BRACKET RH (WCP)	Not Necessary	70.00 F	*- F
19	1	NA	*FRT BUMPER BRACKET LH (WCP)	Broken	70.00 F	*70.00 F
20	1	NA	*HEADLAMP BRACKET RH (WCP)	Not Necessary	70.00 F	*- F
21	1	NA	*HEADLAMP BRACKET LH (WCP)	Not Necessary	70.00 F	*- F
22	1	NA	*BUMPER LOWER LIPS (WCP)	Not Necessary	200.00 F	*- F
23	1	NA	*FOGLAMP RH (WCP)	Not Necessary	160.00 F	*- F
24	1	NA	*FOGLAMP LH (WCP)	Broken	160.00 F	*160.00 F
25	1	NA	*FRT SUPPORT ASSY (WCP)	Repair	900.00 F	*- F
Supplementary #1						
26	1		*BUMPER LOWER GRILLE (WCP)	Deformed	110.00 F	*110.00 F

F=Franchise part.

Sub Total (\$\$)

8,830.00

6,220.00

Report was unsubmitted during this print-out.

10/11/22, 3:08 PM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				+ Margin on L,N Items 10.00/10.00% (S\$)	883.00	622.00
				Total Parts (S\$)	9,713.00	6,842.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BUMPER CLIPS (Necessary)	80.00	30.00
2	1	GRILLE CLIPS (Necessary)	80.00	20.00
3	1	NO PLATE W/CASE (Broken)	-	40.00
Sub Total (\$\$)			160.00	90.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	800.00	450.00
2	SPRAYPAINTING	New	800.00	800.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	100.00	50.00
Gross Labour Cost (\$\$)			1,700.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >