

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22008490/UVY3E2**Date:** 06/10/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001961082
Claimant Vehicle No :	SNC5469S	Insured Vehicle No :	SLN6597P
Date of Loss:	29/08/2022	Nature of Claim:	TP
		Claim No:	283461

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC5469S	Engine No:	CZCC02200
Make & Model:	VOLKSWAGEN GOLF, 1.4 A7 TSI (A)	Chassis No:	WVWZZZAUZKW128981
Reg. Date:	28/06/2019 (Man. Year: 2019)	Odometer:	49678 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,592.72	13,998.73	18,593.99	57.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,810.00	3,290.00	1,520.00	31.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	37,402.72	17,288.73	20,113.99	53.78
Approved Total (Overridden) (\$\$)		13,800.00		
(\$\$)	37,402.72	13,800.00	23,602.72	63.10
+ GST 7.00/7.00% (\$\$)	2,618.19	966.00	1,652.19	63.10
Nett Amount (\$\$)	40,020.91	14,766.00	25,254.91	63.10

INSPECTION

Date of Assignment:	31/08/2022	Automobile Integrated Management Pte Ltd (HQ)
Date Inspected:	31/08/2022 Inspected At:	23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing)
Estimated Period of Repair:	8.0 days	Singapore 415933

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Oct 2022)
Parts:	143	VOLKSWAGEN GOLF 1.4 A7 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC5469S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented / Bent	1,999.60 FL	*1,838.60 FL
2	1		*TAILGATE GLASS	Not Necessary	1,011.42 FL	*- FL
3	1		*TAILGATE EMBLEM GOLF	Necessary	110.24 FL	*90.80 FL
4	2		*TAILGATE LAMPS - L/R	Not Necessary	1,601.84 FL	*- FL
5	1		*TAILGATE INNER LOCK	Not Necessary	300.31 FL	*- FL
6	1		*TAILGATE INNER TRIM BOARD	Not Necessary	588.93 FL	*- FL
7	1		*TAILGATE W/STRIP	Twisted	261.66 FL	*162.00 FL
8	1		*TAILLAMPS - L/R	O/S Cracked / N/SNotNecessary	1,801.58 FL	*745.00 FL
9	1		*REAR BUMPER	Distorted	1,700.70 FL	*1,066.32 FL
10	1		*REAR BUMPER DIFUSSER	Distorted	600.93 FL	*388.20 FL
11	1		*REAR BUMPER PDC SENSORS (4PCS)	Shorted (1Pc Only)	562.66 FL	*205.00 FL
12	1		*REAR BUMPER CHROME MOULDING - CTR	Necessary	399.75 FL	*248.00 FL
13	2		*REAR BUMPER CHROME MOULDINGS - L/R	Necessary	363.24 FL	*230.00 FL
14	2		*REAR BUMPER SIDE RETAINERS - L/R	Not Necessary	179.90 FL	*- FL
15	2		*REAR BUMPER REFLECTOR - L/R	Not Necessary	263.20 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	600.97 FL	*492.30 FL
17	1		*REAR BUMPER CTR GUIDE	Cracked	190.65 FL	*181.00 FL
18	2		*REAR BUMPER SIDE GUIDES - L/R	Not Necessary	179.90 FL	*- FL
19	2		*REAR BUMPER LICENCE LAMPS	Not Necessary	117.20 FL	*- FL
20	1		*REAR BUMPER TOW COVER	Not Necessary	28.60 FL	*- FL
21	1		*REAR END PANEL	Repair	1,399.70 FL	*- FL
22	1		*REAR END PANEL GARNISH	Not Necessary	280.63 FL	*- FL
23	1		*REAR EXHAUST SILENCER	Not Necessary	1,760.50 FL	*- FL
24	3		*REAR EXHAUST MOUNTINGS	Not Necessary	64.50 FL	*- FL
25	1		*REAR EXHAUST INSULATOR	Not Necessary	180.95 FL	*- FL
26	1		*FRONT BONNET	Dented	1,800.12 FL	*1,591.50 FL
27	1		*FRONT BONNET LOCK	Twisted	399.20 FL	*265.00 FL
28	1		*FRONT BONNET LOCK STRIKER	Not Necessary	105.11 FL	*- FL
29	1		*FRONT BONNET DAMPER	Not Necessary	280.93 FL	*- FL
30	2		*FRONT BONNET SEAL - L/R	Not Necessary	137.30 FL	*- FL
31	2		*FRONT BONNET HINGES - L/R	Not Necessary	220.50 FL	*- FL
32	1		*FRONT BUMPER	Dented / Deformed	1,666.91 FL	*1,076.45 FL
33	1		*FRONT BUMPER LOWER GRILLE	Twisted	388.95 FL	*262.42 FL
34	1		*FRONT BUMPER CHROME MOULDING - CTR	Not Necessary	233.71 FL	*- FL
35	2		*FRONT BUMPER CHROME MOULDINGS - L/R	Not Necessary	362.86 FL	*- FL
36	1		*FRONT BUMPER PDC SENSORS (2PCS)	Shorted (1Pc Only)	562.66 FL	*205.00 FL
37	2		*FRONT BUMPER FOG LAMPS - L/R	Not Necessary	963.10 FL	*- FL
38	2		*FRONT BUMPER SPONGE	Torn	199.63 FL	*118.00 FL
39	1		*FRONT BUMPER REINFORCEMENT	Bent	600.97 FL	*492.50 FL
40	2		*FRONT BUMPER SIDE RETAINERS - L/R	Bent	137.70 FL	*90.00 FL
41	1		*FRONT GRILLE	Cracked	700.71 FL	*551.20 FL
42	1		*FRONT GRILLE LOGO	Cracked	188.98 FL	*145.00 FL
43	2		*FRONT HEADLAMPS - L/R	Cracked	4,667.40 FL	*4,175.90 FL
44	2		*FRONT HEADLAMP TOP PANELS - L/R	Repair	285.00 FL	*- FL
45	1		*FRONT SUPPORT PANEL	Cracked	700.12 FL	*580.00 FL

Report was unsubmitted during this print-out.

10/6/22, 11:38 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*FRONT SUPPORT TOP GARNISH	Cracked	120.62 FL	*120.62 FL
47	1		*AIR CLEANER INTAKE	Not Necessary	211.50 FL	*- FL
48	1		*AIR CON CONDENSER	Not Necessary	999.79 FL	*- FL
49	1		*LOW TEMP RADIATOR	Not Necessary	990.71 FL	*- FL
50	1		*HIGH TEMP RADIATOR	Not Necessary	990.71 FL	*- FL
51	1		*RADIATOR AUXILIARY ASSY	Not Necessary	1,260.50 FL	*- FL
52	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
53	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
54	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
55	1		*SET FRONT NO. PLATE WITH HOLDER	Bent	65.00 FS	*40.00 FS
56	1		*SET REAR NO. PLATE WITH HOLDER	Bent	65.00 FS	*40.00 FS
57	1		*BOT A/C OIL	Not Necessary	60.00 FS	*- FS
58	1		*BOT RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)						36,165.25 15,530.81
- List Item Discount on L Items 10.00/10.00% (S\$)						3,572.53 1,532.08
Total Parts (S\$)						32,592.72 13,998.73
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIX TAILGATE GLASS	New	180.00	120.00
2	TO CHECK FRONT & REAR ELECTRICAL WIRING	New	80.00	30.00
3	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	80.00
4	TO REMOVE, REFIX REAR EXHAUST SYSTEMS	New	100.00	0.00
5	TO RESPRAY UNDERCOATING	New	150.00	80.00
6	TO REMOVE, REFIX A/C CONDENSER & REFILL A/C GAS	New	180.00	100.00
7	TO RESPRAY PAINTING AND ETC	New	1,800.00	1,680.00
8	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	2,200.00	1,200.00
Gross Labour Cost (\$\$)			4,810.00	3,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >