



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 5988P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
1	PLATE, BACK DOOR (SN)	NECESSARY	57.50	57.50
1	PLATE, BACK DOOR (SN)	NECESSARY	59.10	59.10
1	COVER, RR BUMPER (SN)	DENTED	549.70	549.70
1	COVER, RR BUMPER (SN)	CUT	455.70	455.70
2	RETAINER, ULTRASONIC (SN)	NECESSARY	72.00	72.00
1	RETAINER, ULTRASONIC (SN) (ADDITIONAL)	NECESSARY	36.00	36.00
1	RETAINER, ULTRASONIC (SN) (ADDITIONAL)	NECESSARY	36.00	36.00
			1,316.00	1,296.00
	<u>LABOUR</u>			
	REPAIR TAIL-GATE DENTED. REPLACE AND REALIGN REAR BUMPER.		900.00	720.00
	SPRAY PAINT ON TAIL-GATE AND REAR BUMPER.		1,475.00	1,180.00
	LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON TAIL-GATE AND REAR BUMPER.		183.18	183.18
	DRILL HOLE TO INSTALL REVERSE SENSOR.		180.00	180.00
	RESET AND REPROGRAMME ECU.		180.00	180.00
			2,918.18	2,443.18
	GRAND TOTAL		4,234.18	3,739.18
	RECOMMENDED COST OF REPAIRS			3,739.18

Report Ref No. CS/SMR22008494/Evy3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.