



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 1250Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	LH TAILLAMP	SERVICEABLE	285.00	-
1	LH FRONT DOOR	BENT	1,170.00	1,170.00
1	LH REAR DOOR	BENT	1,170.00	1,170.00
1	LH FRONT DOOR OUTER HANDLE	DENTED	158.00	158.00
1	LH FRONT DOOR OUTER HANDLE CAP	SERVICEABLE	35.00	-
2	LH DOOR HINGES @\$135.00	TO REPAIR SEE LABOUR	270.00	-
	LESS 20% DISCOUNT		-617.60	-499.60
			2,470.40	1,998.40
<b>LABOUR</b>				
	TO REMOVE AND REFIT DOOR GLASS.		180.00	120.00
	TO KNOCK JACKOUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF LH DOOR HINGES.		750.00	500.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		900.00	750.00
			1,830.00	1,370.00
<b>GRAND TOTAL</b>			<b>4,300.40</b>	<b>3,368.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,700.00</b>

Report Ref No. CS/SMR22008495/Kvy3m4

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.