

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008503/ANY3Q2**Date:** 06/10/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00061432201

Claimant Vehicle No : GBH4025L **Insured Vehicle No :** SFX1115Z

Date of Loss: 20/08/2022 Nature of Claim: TP Claim No: SNM22D206008/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH4025L**

Make & Model: PEUGEOT PARTNER, 1.6 D L2 (A) Engine No: 10JBHW3018735

Reg. Date: 21/05/2018 (Man. Year: 2017) Chassis No: VF37FBHYMHJ752462

Colour: Grey Odometer: 110077 km

Engine Capacity: 1560 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,315.00	4,718.30	5,596.70	54.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	1,570.00	2,780.00	63.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,665.00	6,288.30	8,376.70	57.12
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	14,665.00	5,000.00	9,665.00	65.91

INSPECTION

Date of Assignment: 31/08/2022

Date Inspected: 01/09/2022 Inspected At: POWER BUILD TECHNOLOGY ENGINEERING SERVICES
2 KAKI BUKIT AVENUE 2
#01-36 KAKI BUKIT AUTOHUB,
SINGAPORE 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 04 Oct 2022)**Parts:** N/A PEUGEOT PARTNER 1.6 D L2 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBH4025L)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Dented	1,850.00 F	*1,550.00 FL
2	1		*REAR DOOR RH	Repair	1,850.00 F	*- FL
3	1		*REAR DOOR WEATHERSTRIP	Not Necessary	345.00 F	*- FL
4	1		*REAR DOOR LH UPPER HINGE	Not Necessary	289.00 F	*- FL
5	1		*REAR DOOR LH LOWER HINGE	Not Necessary	289.00 F	*- FL
6	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	295.00 F	*- FL
7	1		*REAR DOOR LH LOCK	Damaged	245.00 F	*245.00 FL
8	1		*REAR DOOR RH LOCK CATCH	Not Necessary	95.00 F	*- FL
9	1		*REAR DOOR EMBLEM	Necessary	89.00 F	*89.00 FL
10	1		*REAR NUMBER PLATE	Bent	60.00 FS	*30.00 FS
11	1		*REAR NUMBER PLATE HOLDER	Deformed	80.00 FS	*30.00 FS
12	1		*REAR LH TAILLAMP	Cut	780.00 F	*235.00 FL
13	2		*REAR NUMBER PLATE LAMP ASSY	Damaged	360.00 F	*120.00 FL
14	1		*REAR BUMPER ASSY	Deformed	980.00 F	*980.00 FL
15	1		*REAR BUMPER REINFORCEMENT	Dented	750.00 F	*440.00 FL
16	2		*REAR BUMPER BRACKET	Necessary	178.00 F	*178.00 FL
17	1		*REAR END PANEL	Dented	650.00 F	*650.00 FL
18	1		*REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
19	1		*REAR REVERSE CAMERA	Damaged	680.00 FS	*380.00 FS
20	1		*REAR DOOR GLASS SEALANT	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,315.00	5,167.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	448.70
Total Parts (\$)	10,315.00	4,718.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO DIMANTLE AND REFIX PANEL BEATING ,STRAIGHTENING ,REALIGNMENT ,REWELD ,RECUT TO FACILITATE REPLACEMENT OF REAR DAMAGED PARTS	New	1,750.00	800.00
2	LABOUR CHARGES FOR SPRAY PAINTING ON ALL AFFECTED DAMAGED PORTION AND REPLACEMENT PARTS	New	1,450.00	600.00
3	LABOUR CHARGES TO REMOVE AND REINSTALL REAR DOOR GLASS	New	200.00	60.00
4	LABOUR CHARGES FOR CHECKING ALL LIGHTING SYSTEM ,REINSTALL REAR REVERSE SENSORS AND REVERSE CAMERA	New	450.00	50.00
5	LABOUR CHARGES TO APPLY RUST PROOFING CHEMICALS AND BODY SEALANT TO ALL DAMAGE PARTS	New	500.00	60.00
Gross Labour Cost (\$\$)			4,350.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >