



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH1412
Vehicle No.	: YQ6874U
Make & Model	: TOYOTA DYNA 150 5MT

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Front Windscreen rubber seal / TN		\$100.00	
1	Wiper arm rh / BT		\$70.00	
1	Wiper arm cover rh / MIS		\$10.00	
1	Wiper panel / DD		\$140.00	
1	Front panel / DD		\$450.00	
1	Front side panel rh / MIS		\$95.00	
1	Front side panel clips @4*\$3 / MC		\$12.00	
1	Center grille assy / BR		\$280.00	
1	Center grille logo badge / MC		\$45.00	
1	Center grille clips @10*\$3 / MC		\$30.00	
1	Headlamp rh / BR		\$290.00	
1	Front bumper / BR		\$220.00	
1	Front bumper fog lamp cover rh / BR		\$60.00	
1	Front bumper side bracket rh / BT		\$100.00	
1	Side mirror rh / CUT		\$75.00	
1	Front door rh / DD		\$580.00	
1	Front door lower hinge rh / BT		\$45.00	
1	Front door window side garnish rh / CUT		\$50.00	
1	Front door weatherstrip / CRM		\$90.00	
1	Front door lower rubber seal / TN		\$35.00	
1	Step up garnish / BR		\$120.00	
1	Step up garnish bracket / BT		\$120.00	
1	Wheel arch rubber seal Rh / TN		\$25.00	
1	Wheel arch front mudflap panel rh / DD		\$130.00	
1	Wheel arch rear mudflap rh / CRM		\$90.00	
1	Wheel arch rear mudflap lower rubber shield rh / TN		\$90.00	
1	Wheel arch rear mudflap bracket rh / BT		\$180.00	
1	Air cleaner box / BR		\$270.00	
1	Brake air vacuum box / DD		\$180.00	
1	Brake air vacuum box sensor / BR		\$70.00	
1	Steering rack control box / ?		\$1,800.00	

1	Front absorber rh ?				\$70.00	
1	Front lower arm ?				\$240.00	
1	Front lower arm ball joint ?				\$75.00	
1	Front upper arm ?				\$320.00	
1	Front knuckle arm ?				\$240.00	
1	Rack end rh / 07				\$75.00	
1	Tie rod end Rh / 07				\$75.00	
1	Front door pillar RH (Repair refer to labour)				\$0.00	
1	Front floor panel (Repair refer to labour)				\$0.00	
1	A pillar RH (Repair refer to labour)				\$0.00	
		Part Items Total:			\$6,947.00	
			15%		\$1,042.05	
					\$7,989.05	
<u>SPECIAL NETT ITEMS</u>						
1	Front bumper clips / NR				\$35.00	
1	Front panel sealant / NR				\$60.00	
1	IU Sticker / NR				\$10.00	
		SN Items Total:			\$105.00	
		Total Parts:			\$8,094.05	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH1412
Vehicle No.	: YQ6874U
Make & Model	: TOYOTA DYNA 150 5MT

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1400.00	1200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1400.00	1000
3	To remove and repair/refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
4	To remove and replace Front windscreen	100.00	/
5	To remove and replace front undercarriage RH	200.00	/
6	To remove and refit/replace front door RH fitting, trimmings, garnish, window glass and lock mechanism	150.00	50
7	To carried out wheel alignment	80.00	/
Labour Total :		3390.00	
TOTAL (PARTS & LABOUR):		11484.05	

Steve (LKK)
31/8/22, 11.00

OD- L1 / LL
EXPERI- ?
PIP
by RL y
10 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Signature: _____ is subject to final approval from insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____