7/18/23, 10:36 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIS22008505/KPA3Q2

18/07/2023 Date:

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2001574331

Claimant Vehicle SLP9996R **Insured Vehicle No:** SJQ717H

No:

Date of Loss: 16/08/2022 Nature of Claim: TP Claim No: 202222006219

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP9996R

HONDA SHUTTLE, 1.5 G (A) Make & Model: Engine No: L15B3539025 Reg. Date: 28/04/2017 (Man. Year: 2016) Chassis No: GK81007708 Odometer: 127411 km Colour: White

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

205/50 R16 Front Tyre Size: 205/50 R16 Rear Tyre Size: Front Left Side: Continental 9 mm Rear Left Side: Continental 9 mm Front Right Side: Rear Right Side: Continental 9 mm Continental 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,486.00	2,486.00	0.00	0.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		980.00	800.00	180.00	18.37
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	3,466.00	3,286.00	180.00	5.19
	+ GST 7.00/7.00% (S\$)	242.62	230.02	12.60	5.19
	Nett Amount (S\$)	3,708.62	3,516.02	192.60	5.19
	+ Loss of Use (4.0 x	S\$60.00/day) (S\$)	240.00		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	3,758.02		

INSPECTION

Date of Assignment: 31/08/2022

Cheng Hoe Motor Pte Ltd (Yishun) Date Inspected: 13/09/2022 Inspected At:

Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: **CHEW HSIAO TONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 17 Jul 2023)

Parts: N/A HONDA SHUTTLE 1.5 G (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLP9996R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Cracked	600.00 F	*600.00 F
2	1		*FRONT BUMPER RH SIDE RETAINER (WCP)	Distorted	8.00 F	*8.00 F
3	2		*FRONT BUMPER CLIPS (WCP)	Necessary	12.00 F	*12.00 F
4	1		*FRONT RH FENDER (WCP)	Bent	150.00 F	*150.00 F
5	1		*RH HEADLAMP (WCP)	Cut	1,490.00 F	*1,490.00 F
F=Fra	anchise	part.		-		
				Sub Total (S\$)	2,260.00	2,260.00
			+ Margin on L,N Ite	ms 10.00/10.00% (S\$) _	226.00	226.00
				Total Parts (S\$)	2,486.00	2,486.00
			Report was unsubmitted during thi	s print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	REMOVE & REFIX FRT BUMPER ASSY ,FRT RH FENDER ,RH HEADLAMP ,KNOCK & REPAIR RH HEADLAMP PANEL AND REALIGN THE SAME	New	480.00	400.00					
2	PUTTY & RESPRAY ON FRT BUMPER ,FRT RH FENDER ,HEADLAMP PANEL	New	500.00	400.00					
	Gross Labour	Cost (S\$)	980.00	800.00					
	Report was unsubmitted during this print-out.								

< END OF ESTIMATES >