

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22008509/RPA3Q2**Date:** 18/07/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001198469
Claimant Vehicle No :	SMH8514K	Insured Vehicle No :	SMJ8451Y
Date of Loss:	28/06/2022	Nature of Claim:	TP
		Claim No:	202222005408

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH8514K	Engine No:	2ZR0C87965
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU90J036570
Reg. Date:	12/02/2019 (Man. Year: 2018)	Odometer:	277641 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,019.25	1,191.50	4,827.75	80.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,310.00	860.00	2,450.00	74.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,329.25	2,051.50	7,277.75	78.01
Approved Total (Overridden) (\$\$)		1,650.00		
Nett Amount (\$\$)	9,329.25	1,650.00	7,679.25	82.31
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	31/08/2022	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat #05-67/68, Carros Centre Singapore 737869
Date Inspected:	31/08/2022 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2023)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH8514K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,359.00 FL	*- FL
2	1		*TAILGATE LOGO	Not Necessary	96.00 FL	*- FL
3	1		*TAILGATE EMBLEM PRIUS	Necessary	96.00 FL	*96.00 FL
4	1		*TAILGATE EMBLEM HYBRID	Necessary	96.00 FL	*96.00 FL
5	1		*TAILGATE WEATHERSTRIP	Not Necessary	258.00 FL	*- FL
6	1		*TAILGATE LOCK	Not Necessary	480.00 FL	*- FL
7	1		*TAILGATE WINDSCREEN GLASS MOULDING	Not Necessary	198.00 FL	*- FL
8	1		*TAILLAMP LH	Not Necessary	480.00 FL	*- FL
9	1		*REAR BUMPER	Cracked	798.00 FL	*549.00 FL
10	2		*REAR BUMPER SIDE RETAINER	Not Necessary	256.00 FL	*- FL
11	2		*REAR BUMPER LAMP	Not Necessary	960.00 FL	*- FL
12	2		*REAR BUMPER BRACKET	Not Necessary	224.00 FL	*- FL
13	1		*REAR BUMPER LOWER LIP	Cut	698.00 FL	*541.00 FL
14	1		*REAR BUMPER UNDER COVER	Not Necessary	64.00 FL	*- FL
15	1		*REAR END PANEL	Not Necessary	656.00 FL	*- FL
16	1		*REAR END PANEL TOP GARNISH	Not Necessary	288.00 FL	*- FL
17	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	312.00 FL	*- FL
18	1		*SET REAR REVERSE SENSOR	Cut	250.00 FS	*200.00 FS
19	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
20	1		*SET REAR END PANEL GARNISH CLIP	Not Necessary	30.00 FS	*- FS
21	1		*END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
22	2		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,849.00	1,512.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,829.75	320.50
Total Parts (\$\$)	6,019.25	1,191.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL WIRING	New	80.00	0.00
2	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	60.00
3	REMOVE AND REFIX REAR UPHOLSTERY	New	150.00	0.00
4	REMOVE AND TRANSFER ALL REAR TAILGATE FITTING	New	150.00	0.00
5	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	180.00	0.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	0.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	400.00
8	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	400.00
Gross Labour Cost (S\$)			3,310.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >