

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22008510/RPA3Q2
Date: 16/03/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001071713
Claimant Vehicle No :	SJL8375J	Insured Vehicle No :	SKF7425A
Date of Loss:	26/08/2022	Nature of Claim:	TP
		Claim No:	202222006444

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL8375J	Engine No:	L13A4114763
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61102871
Reg. Date:	12/12/2008 (Man. Year: 2008)	Odometer:	113283 km
Colour:	Black		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,088.58	3,699.52	8,389.06	69.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,290.00	1,960.00	2,330.00	54.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,378.58	5,659.52	10,719.06	65.45
Approved Total (Overridden) (S\$)		4,500.00		
	(S\$)	16,378.58	4,500.00	11,878.58
+ GST 7.00/7.00% (S\$)		1,146.50	315.00	831.50
Nett Amount (S\$)	17,525.08	4,815.00	12,710.08	72.53
+ Loss of Use (8.0 x S\$50.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		33.00		
+ Other Costs (S\$)		70.00		
Nett Liability (S\$)		5,318.00		

INSPECTION

Date of Assignment:	31/08/2022	
Date Inspected:	31/08/2022 Inspected At:	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat, Carros Centre #05-21 Singapore 737869
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2023)
Parts: 144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJL8375J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Buckled	998.00 FL	*796.00 FL
2	1		*TAIL GATE STOPPER	Necessary	28.50 FL	*28.50 FL
3	1		*TAIL GATE INNER LOCK	Cut	289.00 FL	*186.30 FL
4	1		*TAIL GATE WIPER MOTOR	Not Necessary	589.00 FL	*- FL
5	2		*TAIL GATE ABSORBER	Not Necessary	272.40 FL	*- FL
6	2		*TAIL GATE HINGE	Not Necessary	62.00 FL	*- FL
7	1		*TAIL GATE DETECTOR	Not Necessary	154.00 FL	*- FL
8	1		*TAIL GATE WEATHERSTRIP	Necessary	154.00 FL	*148.40 FL
9	1		*TAIL GATE INNER TRIM	Cracked	258.00 FL	*190.20 FL
10	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	110.00 FL	*110.00 FL
11	1		*TAIL GATE OUTER GARNISH	Not Necessary	184.00 FL	*- FL
12	1		*TAIL GATE OUTER GARNISH LOGO	Not Necessary	58.00 FL	*- FL
13	2		*TAIL GATE REFLECTOR	Not Necessary	622.00 FL	*- FL
14	1		*TAIL GATE EMBLEM FIT	Necessary	35.00 FL	*35.00 FL
15	1		*REAR BUMPER	Deformed	659.00 FL	*490.00 FL
16	2		*REAR BUMPER SIDE GARNISH	Not Necessary	242.00 FL	*- FL
17	1		*REAR BUMPER CENTER GARNISH	Not Necessary	124.00 FL	*- FL
18	2		*REAR BUMPER SIDE RETAINER	Necessary	90.00 FL	*70.40 FL
19	2		*TAIL LAMP	Cracked	978.00 FL	*676.20 FL
20	1		*REVERSE SIREN	Not Necessary	121.00 FL	*- FL
21	2		*REAR FENDER INNER TRIM (LOWER)	Cracked	778.00 FL	*597.80 FL
22	2		*REAR FENDER INNER SHIELD	Not Necessary	179.20 FL	*- FL
23	1		*REAR END PANEL	Bent	542.00 FL	*356.70 FL
24	1		*REAR FLOOR PANEL	Repair	985.00 FL	*- FL
25	1		*REAR FLOOR TOP BOARD	Deformed	415.00 FL	*275.40 FL
26	1		*REAR END PANEL TOP GARNISH	Cracked	101.00 FL	*101.00 FL
27	1		*REAR TOOLS TOOLS BOX COMPARTMENT	Not Necessary	421.00 FL	*- FL
28	2		*REAR EXHAUST MOUNTING	Not Necessary	76.00 FL	*- FL
29	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
30	10		*REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
31	4		*TAIL LAMP CLIP	Necessary	34.00 FS	*20.00 FS
32	2		*TAIL LAMP PANEL SEALANT	Not Necessary	160.00 FS	*- FS
33	2		*TAIL LAMP INNER PANEL SEALANT	Not Necessary	160.00 FS	*- FS
34	1		*TAIL GATE SEALANT	Necessary	80.00 FS	*40.00 FS
35	1		*TAIL GATE INNER TRIM CLIP	Necessary	78.00 FS	*40.00 FS
			(12 PCS)			
36	1		*TAIL GATE WINDSCREEN SEALANT }	Necessary	80.00 FS	*60.00 FS
37	1		*TAIL GATE WINDSCREEN INNER SEAL }	Necessary	80.00 FS	*- FS
38	2		*REAR FENDER SEALANT	Not Necessary	160.00 FS	*- FS
39	12		*REAR FENDER INNER SHIELD CLIP	Not Necessary	78.00 FS	*- FS
40	19		*REAR FENDER INNER TRIM CLIPS	Not Necessary	123.50 FS	*- FS
41	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*40.00 FS
42	1		*REAR EXHAUST AFTER MARKET	Repair	2,500.00 FS	*- FS
43	1		*REVERSE SENSOR	Not Working	220.00 FS	*220.00 FS
44	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (S\$)	13,993.60	4,511.90
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,905.02	812.38
					Total Parts (S\$)	12,088.58	3,699.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,600.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	180.00	60.00
4	WIRING CHECK	New	60.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	300.00	0.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	250.00	60.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	200.00	0.00
8	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
9	TRANFER TAILGATE MECHANISM	New	80.00	60.00
10	CONDUCT WATER LEAKAGE TEST	New	100.00	30.00
			Gross Labour Cost (S\$)	4,290.00
				1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >