

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008515/KPA3Q2**Date:** 06/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900005428
Claimant Vehicle No :	SNB3375Y	Insured Vehicle No :	SMH8194A
Date of Loss:	12/07/2022	Nature of Claim:	TP
		Claim No:	2167649966SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB3375Y	Engine No:	2ZR2H41095
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU603093295
Reg. Date:	16/08/2021 (Man. Year: 2020)	Odometer:	77648 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 9 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50.00	0.00	50.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	550.00	550.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,150.00	550.00	600.00	52.17
+ GST 7.00/7.00% (S\$)	80.50	38.50	42.00	52.17
Nett Amount (S\$)	1,230.50	588.50	642.00	52.17
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		835.95		

INSPECTION

Date of Assignment:	01/09/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	01/09/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Estimated Period of Repair:	2.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (NPA)	Repair	0.00 FL	*- FL
2	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
3	1		*REAR DOOR RH (NPA)	Repair	0.00 FL	*- FL
4	1		*REAR RIM COVER RH (NPA)	Repair	0.00 FL	*- FL
5	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (S\$)	50.00 0.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	0.00 0.00
					Total Parts (S\$)	50.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX REPAIR & READJUST ACCIDENT AREAS	New	300.00	150.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS	New	700.00	400.00
3	TO TUFF KOTE & UNDERSEAL MATERIALS	New	100.00	0.00
Gross Labour Cost (\$\$)			1,100.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >