



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 6288A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	REAR TAILLAMPS @\$630.00	NOT NECESSARY	1,260.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	755.00	-
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	280.00	-
1	REAR BUMPER	DENTED / DEFORMED	2,250.00	2,250.00
2	REAR SIDE BRACKETS @\$180.00	NOT NECESSARY	360.00	-
1	REAR BUMPER CENTRE GUIDE	TWISTED / CRACKED	292.00	292.00
1	REAR BUMPER LOWER DIFFUSER	DEFORMED / TWISTED	480.00	480.00
2	REAR BUMPER REFLECTORS @\$90.00	NOT NECESSARY	180.00	-
1	REAR BUMPER REINFORCEMENT	BENT	722.00	722.00
2	REAR BUMPER SIDE RETAINERS @\$120.00	NOT NECESSARY	240.00	-
4	REAR BUMPER PDC SENSORS @\$225.00	SHORTED (1 PCS ONLY)	900.00	225.00
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	45.00	-
2	REAR BUMPER NUMBER PLATE LAMPS @\$60.00	NOT NECESSARY	120.00	-
	LESS 10% DISCOUNT		-788.40	-396.90
			7,095.60	3,572.10
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	55.00	55.00
1	REAR NUMBER PLATE WITH HOLDER (SN)	BENT	50.00	40.00
1	REAR REVERSE CAMERA (SN)	SERVICEABLE	380.00	-
			485.00	95.00
<u>LABOUR</u>				
	TO REMOVE AND REFIT DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	20.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR .		180.00	50.00
	TO APPLY UNDERCOATING.	NOT NECESSARY	200.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		800.00	450.00

Report Ref No. CS/AGI22008521/Uvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING ON AFFECTED AREAS .		800.00	600.00
			2,060.00	1,120.00
GRAND TOTAL			9,640.60	4,787.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CS/AGI22008521/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.