

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008529/DVY3Q2**Date:** 11/01/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00006882202
Claimant Vehicle No :	SJG5389R	Insured Vehicle No :	YP9586L
Date of Loss:	31/08/2022	Nature of Claim:	TP
		Claim No:	SNM22D206192/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG5389R	Engine No:	1ZZ3123969
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100413803
Reg. Date:	03/07/2008 (Man. Year: 2008)	Odometer:	122418 km
Colour:	Grey		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,830.60	4,373.35	15,457.25	77.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,350.00	1,930.00	5,420.00	73.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,180.60	6,303.35	20,877.25	76.81
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	27,180.60	5,000.00	22,180.60	81.60
+ GST 7.00/7.00% (S\$)	1,902.64	350.00	1,552.64	81.60
Nett Amount (S\$)	29,083.24	5,350.00	23,733.24	81.60

INSPECTION

Date of Assignment:	01/09/2022	
Date Inspected:	02/09/2022 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: BRYAN TANI**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2023)
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJG5389R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,610.10 FL	*1,480.00 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	192.70 FL	*170.00 FL
3	1		*TAILGATE LOGO	Necessary	80.20 FL	*80.20 FL
4	1		*TAILGATE CENTER CHROME MOULDING	Cracked	439.10 FL	*387.50 FL
5	2		*TAILGATE NO PLATE LAMP LH/RH	Not Necessary	184.20 FL	*- FL
6	1		*TAILGATE LOCK	Damaged	343.50 FL	*343.50 FL
7	1		*TAILGATE SWITCH	Not Necessary	188.55 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Necessary / Torn	304.00 FL	*288.00 FL
9	1		*SET TAILGATE STOPPERS	Serviceable	36.40 FL	*- FL
10	1		*TAILGATE INNER TRIM BOARD	Mtg Broken	928.20 FL	*379.20 FL
11	2		*TAILGATE LAMP LH/RH	No such part	796.20 FL	*- FL
12	1		*TAILGATE WIPER MOTOR	Not Necessary	672.00 FL	*- FL
13	1		*TAILGATE WIPER ARM	Not Necessary	198.20 FL	*- FL
14	2		*TAILGATE DAMPER LH/RH	Not Necessary	698.00 FL	*- FL
15	2		*TAILGATE HINGE LH/RH	Not Necessary	182.40 FL	*- FL
16	1		*TAILGATE VALVEMATIC EMBLEM	Not fitted	110.20 FL	*- FL
17	2		*TAIL LAMP LH/RH	Cracked / Mtg Broken	1,345.20 FL	*945.20 FL
18	2		*TAIL LAMP PANEL LH/RH	Not Necessary	713.46 FL	*- FL
19	1		*REAR BUMPER	Distorted / Cracked	830.50 FL	*590.00 FL
20	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	179.00 FL	*- FL
21	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	193.80 FL	*- FL
22	1		*REAR END PANEL	Dented	1,090.60 FL	*689.20 FL
23	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	332.96 FL	*245.00 FL
24	1		*REAR FLOOR PANEL EXTENSION	Not Necessary	1,743.10 FL	*- FL
25	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	562.90 FL	*- FL
26	1		*REAR FLOOR PANEL TOOL BOX	Not Necessary	350.27 FL	*- FL
27	2		*REAR FLOOR QUARTER PANEL LH/RH	Not Necessary	647.80 FL	*- FL
28	2		*REAR FENDER LH/RH	Not Necessary	3,077.18 FL	*- FL
29	2		*REAR FENDER QUARTER GLASS MOULDING LH/RH	Not Necessary	858.40 FL	*- FL
30	2		*REAR FENDER INNER TRIM BOARD LH/RH	Not Necessary	1,757.74 FL	*- FL
31	1		*REAR EXHAUST PIPE	Not Necessary	1,198.87 FL	*- FL
32	1		*REAR EXHAUST MOUNTING	Not Necessary	81.50 FL	*- FL
33	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	125.63 FL	*- FL
34	1		*SPARE TYRE BOLT	Not Necessary	297.28 FL	*- FL
35	1		*SPARE TYRE HOLDER	Not Necessary	315.00 FL	*- FL
36	1		*SPARE TYRE BRACKET	Not Necessary	229.00 FL	*- FL
37	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
38	1		*TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
39	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
40	1		*TAILGATE CHROME GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
41	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*15.00 FS
42	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*15.00 FS
43	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
44	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
45	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
49	1		*REAR FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
50	1		*REAR NO.PLATE & CASING	Bent / Cut	100.00 FS	*45.00 FS
51	1		*REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
52	1		*REAR BUMPER LOWER LID	Not fitted	1,200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,554.14	5,772.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,723.54	1,399.45
Total Parts (\$\$)	19,830.60	4,373.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	500.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	800.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	800.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
6	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	New	150.00	0.00
7	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	300.00	120.00
8	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	200.00	0.00
9	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
10	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
11	TO RNR REAR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	300.00	0.00
12	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			7,350.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >