

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008531/UPA3Q2**Date:** 17/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700021889
Claimant Vehicle No :	FBK1698Z	Insured Vehicle No :	SFG1333A
Date of Loss:	23/08/2022	Nature of Claim:	TP
		Claim No:	3172808538SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK1698Z	Engine No:	E3J2E016944
Make & Model:	YAMAHA YBR125, 124cc (M)	Chassis No:	LBPKE1789E0028774
Reg. Date:	13/04/2015 (Man. Year: 2014)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	124 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	2.75-18	Rear Tyre Size:	3.00-18
Front Left Side:	Timsun 7 mm	Rear Left Side:	Timsun 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,016.00	4,490.80	1,525.20	25.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,064.00	435.00	629.00	59.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,080.00	4,925.80	2,154.20	30.43
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	7,080.00	3,200.00	3,880.00	54.80
+ GST 7.00/7.00% (S\$)	495.60	224.00	271.60	54.80
Nett Amount (S\$)	7,575.60	3,424.00	4,151.60	54.80
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,546.00		

INSPECTION

Date of Assignment:	01/09/2022	
Date Inspected:	01/09/2022	Inspected At: Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ALIGNMENT BODY	Not Necessary	380.00 F	*- FL
2	1		*AXLE WHEEL FRONT	Bent	23.00 F	*23.00 FL
3	1		*BAR HANDLE	Bent	49.00 F	*49.00 FL
4	2		*BEARING 6202-DDUCM (NSK)	Necessary	28.00 F	*28.00 FL
5	1		*BRACKET FOOTREST LH	Serviceable	38.00 F	*- FL
6	1		*BRACKET MUDGUARD FRONT	Bent	24.00 F	*24.00 FL
7	1		*BRACKET UNDER FORK	Bent	180.00 F	*180.00 FL
8	1		*CABLE CLUTCH	Damaged	19.00 F	*19.00 FL
9	1		*CABLE SPEEDOMETER	Damaged	14.00 F	*14.00 FL
10	1		*CABLE THROTTLE 1	Damaged	22.00 F	*22.00 FL
11	1		*CABLE THROTTLE 2	Damaged	24.00 F	*24.00 FL
12	1		*CALIPER BRAKE FRONT ASSY	Not Necessary	390.00 F	*- FL
13	1		*CAMERA (V-SYS) M6 (WIFI VERSION)	Damaged	350.00 F	*350.00 FL
14	1		*COVER SIDE LH (BLACK)	Cracked	96.00 F	*96.00 FL
15	1		*COVER SIDE RH (BLACK)	Cracked	96.00 F	*96.00 FL
16	1		*COVER TAIL LH (RED)	Repair	77.00 F	*- FL
17	1		*COVER TANK SIDE LH (BLACK)	Cracked	96.00 F	*96.00 FL
18	1		*COVER TANK SIDE RH (BLACK)	Cracked	96.00 F	*96.00 FL
19	1		*COWLING FRONT (RED)	Distorted	133.00 F	*133.00 FL
20	1		*CRASH BAR	Bent	203.00 F	*203.00 FL
21	1		*CROWN HANDLE	Twisted	75.00 F	*75.00 FL
22	1		*FOOTREST REAR ASSY LH	Not Necessary	15.00 F	*- FL
23	1		*FORK FRONT ASSY LH	Bent	624.00 F	*624.00 FL
24	1		*FORK FRONT ASSY RH	Bent	624.00 F	*624.00 FL
25	1		*GASKET EXHAUST PIPE	Necessary	5.00 F	*5.00 FL
26	1		*HEADLAMP ASSY	Broken	105.00 F	*105.00 FL
27	1		*LAMP SIGNAL FRONT LH	Cracked	21.00 F	*21.00 FL
28	1		*LAMP SIGNAL FRONT RH	Cracked	21.00 F	*21.00 FL
29	1		*LAMP SIGNAL REAR LH	Cracked	21.00 F	*21.00 FL
30	1		*LEVER CLUTCH	Cut	19.00 F	*19.00 FL
31	1		*METER ASSY	Cut	264.00 F	*264.00 FL
32	1		*METER IU (12V) NEW MODEL	Cut	280.00 FS	*165.00 FS
33	1		*MID O-RING	Necessary	3.00 F	*3.00 FL
34	1		*MIRROR LH	Cut	35.00 F	*35.00 FL
35	1		*MUDGUARD FRONT (RED)	Cracked	49.00 F	*49.00 FL
36	1		*PIPE EXHAUST ASSY	Bent	630.00 F	*630.00 FL
37	1		*PLATE DISC BRAKE FRONT	Warped	193.00 F	*193.00 FL
38	1		*PLATE FRONT COWLING	Bent	26.00 F	*26.00 FL
39	1		*RUBBER FOOTREST FRONT	Not Necessary	14.00 F	*- FL
40	1		*STAY HEADLAMP	Bent	68.00 F	*68.00 FL
41	1		*SET STEERING CONE	Necessary	65.00 F	*65.00 FL
42	2		*STICKER (MCDONALDS)SIDE COVER /WINDSHIELD	Necessary	32.00 FS	*32.00 FS
43	1		*STICKER (MCDONALDS)WINDSHIELD V2	Necessary	16.00 FS	*16.00 FS
44	1		*STICKER NUMBER PLATE FRONT (BLACK)	Necessary	19.00 FS	*10.00 FS
45	1		*TANK FUEL (RED)	Dented	441.00 F	*441.00 FL
46	1		*VALVE RIM	Not Necessary	13.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,016.00	4,965.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	474.20
Total Parts (\$)	6,016.00	4,490.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT CHARGES	New	56.00	35.00
2	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	1,008.00	400.00
Gross Labour Cost (\$)			1,064.00	435.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >