

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22008533/KCY3Q2**Date:** 20/10/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SMD4564M **Insured Vehicle No :** SMQ357C

Date of Loss: 19/08/2022 Nature of Claim: TP Claim No: DMPC2200365H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD4564M**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: 27091031682954

Reg. Date: 21/08/2018 (Man. Year: 2018) Chassis No: WDC1569422J528487

Colour: Metallic Black Odometer: 117882 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18

Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,432.30	3,516.80	2,915.50	45.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	575.00	1,725.00	75.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	8,732.30	4,091.80	4,640.50	53.14
+ GST 7.00/7.00% (\$\$)	611.26	286.43	324.83	53.14
Nett Amount (\$\$)	9,343.56	4,378.23	4,965.33	53.14

INSPECTION

Date of Assignment: 01/09/2022

Date Inspected: 01/09/2022 Inspected At: Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Oct 2022)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD4564M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	1,300.00 FN	*1,300.00 FN
2	1		*REAR BUMPER REINFORCEMENT	Bent	678.00 FN	*678.00 FN
3	2		*REAR BUMPER SIDE RETAINER -RH/LH	Serviceable	48.00 FN	*- FN
4	2		*REAR BUMPER REVERSE SENSOR	Serviceable	430.00 FN	*- FN
5	6		*REAR BUMPER REVERSE SENSOR SEAL	Necessary	72.00 FN	*72.00 FN
6	1		*REAR BUMPER LOWER SPOILER	Dented / Cut	652.00 FN	*652.00 FN
7	1		*REAR BUMPER INNER FRAME	Serviceable	82.00 FN	*- FN
8	1		*REAR BUMPER CLIPS (6 PCS)	Necessary	54.00 FS	*50.00 FS
9	1		*REAR BUMPER TOWING COVER	Serviceable	120.00 FN	*- FN
10	1		*REAR BUMPER TOP CHROME	Serviceable	240.00 FN	*- FN
11	1		*REAR END PANEL	Repair	1,467.00 FN	*- FN
12	1		*TAILLAMP ASSY -RH	Serviceable	848.00 FN	*- FN
13	1		*REAR BUMPER LOWER CHROME	Dented / Warped	1,150.00 FN	*1,150.00 FN
					Sub Total (\$\$)	7,141.00 3,902.00
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	708.70 385.20
					Total Parts (\$\$)	6,432.30 3,516.80

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT REAR BUMPER SENSOR	New	100.00	60.00
2	TO CHECK & RECTIFY WIRING SYSTEM	New	80.00	15.00
3	TO PANEL BEAT AND STRAIGHTEN REAR FLOORBOARD PANEL ,REAR CHASSIS FRAME ,TO CUT AND WELD REAR END PANEL ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY TO REFIT AND ADJUST THE THE SAME	New	1,000.00	250.00
4	TO PUTTY & SPRAY PAINT ON AFFECTED AREA	New	1,000.00	250.00
5	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS	New	120.00	0.00
Gross Labour Cost (\$\$)			2,300.00	575.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >