



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 5308R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SKULLCAP,L.ST (SN)	CRUSHED	42.97	42.97
1	MIRROR ASSY,L. (SN)	BROKEN	406.65	406.65
1	PANEL COMPL.FR.DOOR (SN)	DENTED	657.82	657.82
1	TAPE SETL.FR.DOOR (SN)	NECESSARY	26.92	26.92
1	PANEL COMP,L.RR.DOOR (SN)	DENTED	576.07	576.07
1	TAPEL.RR.DOOR SASH (SN)	NECESSARY	11.55	11.55
1	SUNDRIES (SN)	NECESSARY	110.00	50.00
1	HINGEL.RR.DR.UPPER (SN) (ADDITIONAL)	BENT	28.35	28.35
1	HANDLE ASSYL.FR.DOOR (SN) (ADDITIONAL)	CUT	66.97	66.97
			1,927.30	1,867.30
	<u>LABOUR</u>			
	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST.		650.00	650.00
	REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST.		650.00	650.00
	SPRAY PAINTING ON FR R DOOR & RR R DOOR.		2,500.00	1,560.00
	STRAIGHTEN ALIGN FR AND RR L DOOR.		2,500.00	1,300.00
			6,300.00	4,160.00
GRAND TOTAL			8,227.30	6,027.30

RECOMMENDED COST OF REPAIRS				6,027.30
------------------------------------	--	--	--	-----------------

Report Ref No. CS/SMR22008535/Evy3m4

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.