

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008540/KVY3Q2**Date:** 13/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00146632100

Claimant Vehicle No : SKB920D**Insured Vehicle No :** GBL6428Z

Date of Loss: 28/08/2022

Nature of Claim: TP

Claim No: SNM22D206117/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKB920D**

Make & Model: KIA CERATO, 1.6 SX (A)

Engine No: G4FGKH744199

Reg. Date: 19/08/2019 (Man. Year: 2019)

Chassis No: KNAF3416MK5049854

Colour: Metallic Black

Odometer: 83823 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,444.13	1,304.10	2,140.03	62.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	530.00	1,020.00	65.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,994.13	1,834.10	3,160.03	63.27
+ GST 7.00/7.00% (S\$)	349.59	128.39	221.20	63.27
Nett Amount (S\$)	5,343.72	1,962.49	3,381.23	63.27

INSPECTION

Date of Assignment: 01/09/2022

Date Inspected: 05/09/2022 Inspected At:

 Accord Auto Services Pte Ltd (HQ)
 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
 Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2022)
Parts:	143	KIA CERATO 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB920D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent	1,279.00 FL	*1,277.00 FL
2	1		*FRONT RH DOOR HINGE	Repair	51.00 FL	*- FL
3	1		*FRONT RH DOOR CHECKER	Serviceable	40.00 FL	*- FL
4	1		*FRONT RH DOOR STICKER	Necessary	12.00 FL	*12.00 FL
5	1		*FRONT RH DOOR OUTER GARNISH MOULDING @ WINDOW GLASS	Serviceable	72.00 FL	*- FL
6	1		*FRONT RH DOOR INNER TRIM BOARD	Serviceable	630.40 FL	*- FL
7	1		*FRONT RH DOOR RUBBER	Serviceable	92.00 FL	*- FL
8	1		*DOOR STOPPER	Serviceable	3.00 FL	*- FL
9	1		*FRONT RH DOOR WINDOW REGULATOR	Serviceable	218.00 FL	*- FL
10	1		*RH ROCKER PANEL	Repair	1,208.30 FL	*- FL
11	1		*FRONT RH DOOR OUTER HANDLE COVER	Dented	12.00 FL	*12.00 FL
12	1		*FRONT RH DOOR OUTER HANDLE COVER	Dented	148.00 FL	*148.00 FL
13	1		*SET FRONT RH DOOR INNER COMPARTMENT CLIPS	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,820.70	1,449.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	376.57	144.90
Total Parts (\$\$)	3,444.13	1,304.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	400.00	220.00
2	LABOUR REMOVE /REFIX ACCIDENT DAMAGE PARTS TO KNOCK JACK CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	600.00	200.00
3	TO CHECK WIRING SYSTEM	New	100.00	20.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	30.00
5	TO REMOVE /REFIT FRONT RH DOOR WINDOW GLASS ,MECHANISM & ETC TO NEW DOOR	New	150.00	60.00
6	TO REMOVE /REFIX INNER COMPARTMENT TO FACILITATE REPAIR	New	180.00	0.00
Gross Labour Cost (S\$)			1,550.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >