PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191 Mobile 9295 2204 Fax: 6722 8508 Email pasvos@hotmail.com

Business Reg 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0460322

Date of Report

: 18/04/2022

To: M/s. Forte Auto Leasing Pte Ltd

Date of Assignment

: 25/03/2022

C/o. 53. Ubi Ave 1, #05-44

Report requested by

: M/s. Forte Auto Leasing Pte I

Paya Ubi Industrial Park Singapore 408934

Date of Accident Date of Inspection : 21/03/2022

: 25/03/2022

Claim No.

: Third Party Claim

Policy No.

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: SLP8598M

Engine Capacity (cc) : 1496cc

Make & Model

: Mazda 3 1.5

Mileage (km)

: 217013km

Date of Registration

: 21/06/2017

Chassis / Frame No. : JM6BN22A8H0158967

Colour

: Met. Blue

Engine No.

: P520451572

TYRE CONDITION

Front LH

: 6 mm

Front RH

: 6 mm

Make

: Goodrich

Make

: Goodrich

Rear LH

: 6 mm

Rear RH

: 6 mm

Make

: Toyo

Make

: Grenlander

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

: Good

Handbrake

: Serviceable

Footbrake

Serviceable

Steering

Serviceable

Apparent Engine Modification

: Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location

M/s. Neo Automotive Pte Ltd

53, Ubi Ave 1, #05-44, Paya Ubi Industrial Park, Singapore 408934

ASSESSMENT

Repairer's Estimate

14,359.12

Revised Amount

5 12,024.88

Less Excess

Recommended Reserve

9,620.00

(Lump Sum)

: 10 Working Days Estimated Normal Period of Repairs

subant H/s \$7000

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address: My Mail Box 886259 Singapore 919191
Mobile: 9295 2204 Fax: 6722 8508 Email: pasves@hotmail.com

Business Reg. 201404434D

Vehicle No: SLP8598M

Report No.: PAS/TP/0460322

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Neo Automotive Pte Ltd, 53, Ubi Ave 1, #05-44, Paya Ubi Industrial Park, Singapore 408934.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the LHR portion. (The LHR roadwheel was also affected)

DAMAGES

The boot lid, rear bumper, rear end panel, rear floor panel, LHR chassis member, LHR fender, LHR fender inn wheelhouse assy, LH taillamp, LHR reflectors, LHR door, LHR alloy rim, LHR wheel hub assy, LHR knuckle arm, LHR shock absorber, LHR lower arm, LHR trailing arm, LHR control arm, LHR lateral arm, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$12,024.88.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$9.620.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How


Automobile Appraiser

MSAAA

Licensed Appraiser

D--- 7 -F A

PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile. 9295 2204 Fax. 6722 8508 Email: pasvos@hotmail.com Susiness Reg. 201404434D



Vehicle No: SLP8598M

Report No.: PAS/TP/0460322

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition			Repairer's Estimate (S\$)		Our Assessment (S\$)		
			D 1/0			d)	1 002 60	2	ets.	~
1	l pc	Boot lid	Dented/Repair			\$	1,092.60	Nu	\$	- X
2	l pc	Boot lid emblem (Logo)	Necessary			\$	74.40 53.40		\$	74.40
3	I pc	Boot lid emblem (Mazda 3)	Necessary					ner	\$ 5	
4	l pc	Boot lid emblem (SKYACTIV)	Necessary *			\$	63.30			63.30
5	1 pc	Boot reflector lamp LH	Broken			\$	318.60	Cru	S.	318.60
6	1 pc	Taillamp LH	Cracked			\$ \$	598.30 377.80	CNG	S S	598.30 377.80
7	l pc	Taillamp panel LH	Dented			\$	1,074.80	5:15	S	1,074.80
8	1 pc	Rr bumper	Dented	Mississ		\$	38.40		S	38.40
9	1 pc	Rr bumper tow cover LH	Broken/Dislodged/l Broken	viissing				BND	S	60.80
10	1 pc	Rr bumper reflector LH		e.	3.20	\$		Au	5	
11		Rr bumper fastener	Necessary	\$	3.20	S	537.30		\$	19.20
12	l pc	Rr bumper reinforcement	Dented	e	26.10	S		cre/re		537.30
13		Rr bumper retainer R/L	Cracked/Necessary	S	36.10	S		רה		72.20
14	1 pc	Rr end panel	Dented/Distorted			S	586.20 94.30	NH	\$	586.20 ×
15	1 pc	Rr end panel garnish	Dented/Defaced			S	129.40		\$	200
16	1 pc	Rr weatherstrip	Torn/Necessary			S	148.00			129.40
17	1 pc	Rr spare tyre tool sponge	Broken			\$			\$	148.00
18	l pc	Rr windscreen moulding	Necessary			\$	87.60	Dis	\$	87.60
19	1	Rr fender LH	Dented/Buckled			\$	1,274.20	chi	\$	1,274.20
20	l pe	Rr fender air vent LH	Dented/Cracked			\$	71.30		\$	71.30 X
21	l pc	Rr fender inn wheelhouse assy LH	Dented/Distorted			\$	1,092.60	3	\$	1,092.60
22	1 pc	Rr floor side extension LH	Dented/Buckled			\$	133.80	De	\$	133.80
23	1 pc	Rr fender inner trim LH	Deformed/Distorted		2.20	\$	98.40		S	98.40
24		Rr fender inner trim clip LH	Necessary	S	3.20	S		nu	S	19.20
25	1 pc	Rr fender cowling LH	Torn/Deformed	6	2.00	\$	114.30	10-1	5	114.30
26	5 pes	Rr fender cowling clip LH	Necessary	S	3.00	\$	15.00	nu	\$	15.00
27	1 pc	Rr fender lower side cover LH	Cracked/Torn			S	82.60	Tim	\$	82.60
28	1 pc	Rr door LH	Dented/Repair			S	1,062.70	R	\$	-
29	1 pc	Rr alloy rim LH	Dented/Defaced			\$	1.101.70	NH	S	1.101.70 🗶
30	1 pc	Rr shock absorber LH	Bent/Jammed			S	319.40	sul	\$	319.40
31	I pc	Rr wheel hub assy LH	Warped/Damaged			\$	426.90	sul	\$	426.90
32	1 pc	Rr knuckle arm LH	Bent			\$	671.30		S	671.30
33	1 pc	Rr lower arm LH	Bent			\$	271.60		5	271.60
34	1 pc	Rr trailing arm LH	Bent			\$	223,40	***	S	223.40
35	1 pc	Rr control arm LH	Bent			\$	258.20	7 1	\$	258.20
36	1 pc	Rr lateral arm LH	Bent			S	135.70	M	S	135.70
37	1 pc	Boot lid	Dented/Repair							no. 8 & 9)
38	1 pc	Rr chassis member LH	Dented/Repair							no. 8 & 9)
39	1 pc	Rr door LH	Dented/Repair			# Same and the	(R	tefer labo	our	no. 8 & 9)
						S	12,798.90		\$	10.643.60
				Less I	Discount : 20%	\$	2.559.78	20%	\$	2.128.72
			Lis	st Parts St	ub-Total:	S	10,239.12		\$	8,514.88
-	1 pc	Rr windscreen sealant	Necessary		S/N	S	50.00	res	\$	40.00 _
2	1 pc	Rr fender panel sealant LH	Necessary		SN	S	50.00	nu	\$	40.00
3	1 pc	Rr end panel sealant	Necessary		SN	\$	50.00	ru	\$	40.00
4	1	Rr reverse sensor	Dented/Damaged		SN	5	200.00	Turn	S	200.00
5	1 pc	Rr tyre LH (Depreciate 20%)	Cut		SN	S	250.00	M	\$	200.00 💢
6		Brake fluid	Necessary		SN	S		NN	\$	20.00 💢
				Par	ts Total :	\$	10,859.12	orderer in	\$	9,054.88



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address: My Mail Box 886259 Singapore 919191
Mobile 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg 201404434D

Vehic	ele No : SLP8598M	Report No	No.: PAS/TP/0460322			
S/No.	Labour Descriptions		pairer's imate (S\$)	Our Assessment (S\$)		
1	To remove and reinstall electrical wiring system for necessary repairs. To check rear electrical wiring system.	\$	70.00	s	50.00 20	
2	To remove and reinstall rear windscreen for necessary repairs.	s	120.00	\$	120.00	
3	To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs.	S	120.00	S	100.00 %	
4	To remove and reinstall fuel tank, pipings, etc. for necessary repairs.	\$	100.00	· .	80.00 60	
5	To remove, replace and reinstall rear reverse sensors & control unit.	\$	50.00	S	50.00 V	
6	To remove, check and replace LHR undercarriage parts. (Include flush and bleed brakes system)	\$	250.00	\$	120	
7	To conduct wheel alignment.	\$	60.00	S	60.00	
8	To straighten, repair, realign on affected area and replace damaged parts.	\$	1,500.00	S	1,210.00	
9	To spray painting, blending on affected and adjacent area.	S	1,200.00	s	1,050.00/08	
10	To spray anti-rust coating on new and affected panels.	\$	30.00	\$	30.00 /	
	Labour Total :	\$	3,500.00	S	2,970.00	
	Total (Parts & Labour):	\$	14,359.12	go i a con i dispersionali di salamana	12,024.88	

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 9,620.00

Under normal circumstances, the repairs should be completed within a reasonable period of 10 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

99 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.