

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008541/KCY3Q2**Date:** 02/11/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00238142100	
Claimant Vehicle No :	SKX2424R	Insured Vehicle No :	SJQ5995M	
Date of Loss:	29/08/2022	Nature of Claim:	TP	Claim No: SNM22D206196/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX2424R		Engine No:	PE10278723
Make & Model:	MAZDA 5, 2.0 SP.6EAT SUNROOF (A)		Chassis No:	JM6CW1071G0122799
Reg. Date:	30/11/2015 (Man. Year: 2015)		Odometer:	174820 km
Colour:	White			
Engine Capacity:	1998 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,958.80	2,188.08	2,770.72	55.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	1,175.00	845.00	41.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,978.80	3,363.08	3,615.72	51.81
Approved Total (Overridden) (\$\$)		2,650.00		
(\$\$)	6,978.80	2,650.00	4,328.80	62.03
+ GST 7.00/7.00% (\$\$)	488.52	185.50	303.02	62.03
Nett Amount (\$\$)	7,467.32	2,835.50	4,631.82	62.03

INSPECTION

Date of Assignment:	01/09/2022	
Date Inspected:	02/09/2022	Inspected At: Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Nov 2022)	
Parts:	N/A	MAZDA 5 2.0 SP.6EAT SUNROOF (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX2424R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MLDG	Necessary	60.50 FL	*60.50 FL
2	1		*TAILGATE	Bent	1,637.00 FL	*1,637.00 FL
3	1		*TAILGATE EMBLEM	Necessary	44.10 FL	*44.10 FL
4	1		*TAILGATE MAZDA LOGO	Necessary	45.30 FL	*45.30 FL
5	1		*TAILGATE 5 LOGO	Necessary	36.30 FL	*36.30 FL
6	1		*TAILGATE SKYACTIV TECHNOLOGY	Necessary	80.00 FL	*80.00 FL
7	1		*TAILGATE LOCK	Repair	256.20 FL	*- FL
8	1		*TAILGATE LOWER INNER TRIM	Serviceable	432.00 FL	*- FL
9	1		*TAILGATE RUBBER	Serviceable	177.50 FL	*- FL
10	1		*TAILGATE LAMP LH	Serviceable	388.50 FL	*- FL
11	1		*TAILLAMP LH	Serviceable	601.70 FL	*- FL
12	1		*REAR BUMPER	Bent	691.30 FL	*691.30 FL
13	6		*REAR BUMPER CLIPS	Necessary	18.00 FL	*18.00 FL
14	1		*REAR BUMPER REFLECTOR LH	Serviceable	53.00 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Repair	155.40 FL	*- FL
16	1		*REAR BUMPER SIDE RETAINER LH	Distorted	47.60 FL	*47.60 FL
17	1		*REAR BUMPER SPLASH SHIELD LH	Serviceable	39.60 FL	*- FL
18	1		*EXHAUST PIPE TAIL	Repair	1,109.50 FL	*- FL
19	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS
20	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
21	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,133.50	2,720.10
- List Item Discount on L Items 20.00/20.00% (\$)	1,174.70	532.02
Total Parts (\$)	4,958.80	2,188.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REINSTALL /REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES	New	60.00	60.00
4	TO REMOVE AND REINSTALL /REPLACE /REAR BUMPER SENSORS	New	60.00	50.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
6	TO REALIGN DISMANTLE AND REINSTALL /REPLACE EXHAUST PIPE	New	80.00	0.00
7	TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD TO KNOCK & REPAIR REAR END PANEL INNER PANELS AND AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME	New	800.00	500.00
8	TO SPRAY TAILGATE REAR BUMPER ,REAR END PANEL	New	800.00	400.00
Gross Labour Cost (\$\$)			2,020.00	1,175.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >