

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711**Our File No:** CS/III22008547/KVY3E2**Date:** 28/02/2023REFERENCEInsured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326_02
Date of Loss: 13/08/2022 Nature of Claim: OD Claim No: MFL2022D0004707DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SDK8800A**
Make & Model: TOYOTA CAMRY, 2.0 (A) Engine No: 6ARP212540
Reg. Date: 30/12/2016 (Man. Year: 2016) Chassis No: MR053DK5100108774
Colour: Metallic Grey Odometer: 22390 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$78,000.00
Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: YesCONDITION OF TYRESFront Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Davanti 9 mm Rear Left Side: Davanti 9 mm
Front Right Side: Davanti 9 mm Rear Right Side: Davanti 9 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,331.87	10,317.15	8,014.72	43.72
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	3,610.00	2,350.00	1,260.00	34.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,952.87	12,678.15	9,274.72	42.25
Approved Total (Overridden) (S\$)		10,100.00		
- Excess (S\$)	0.00	1,750.00	-1,750.00	
(S\$)	21,952.87	8,350.00	13,602.87	61.96
+ GST 7.00/7.00% (S\$)	1,536.70	584.50	952.20	61.96
Nett Amount (S\$)	23,489.57	8,934.50	14,555.07	61.96

INSPECTIONDate of Assignment: 01/09/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)
ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected: 02/09/2022 Inspected At: 205 Braddell Road
Singapore 579701
Estimated Period of Repair: 7.0 days**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Feb 2023)
Parts: 143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDK8800A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH WING MIRROR ASSY	Serviceable	1,374.90 FL	*- FL
2	1		*FRT RH DOOR	Bent	1,774.10 FL	*1,774.10 FL
3	1		*FRT RH DOOR HINGE TOP	Repair	103.10 FL	*- FL
4	1		*FRT RH DOOR HINGE LOWER	Repair	117.60 FL	*- FL
5	1		*FT RH DOOR CHECKER	Serviceable	195.20 FL	*- FL
6	1		*FRT RH DOOR WINDOW REGULATOR	Serviceable	293.50 FL	*- FL
7	1		*FRT RH DOOR WINDOW MOULDING (CHROME)	Dented	121.10 FL	*121.10 FL
8	1		*FRT RH DOOR FRAME MOULDING (BLACK)	Necessary	83.50 FL	*83.50 FL
9	1		*FRT RH DOOR WHEATHERSTRIP	Serviceable	245.50 FL	*- FL
10	1		*FRT RH DOOR LOCK MECHANISM	Jammed	639.60 FL	*639.60 FL
11	1		*FRT RH DOOR GLASS	Serviceable	909.20 FL	*- FL
12	1		*FRT DOOR HANDLE SEAL 1	Serviceable	38.20 FL	*- FL
13	1		*FRT DOOR HANDLE SEAL 2	Serviceable	38.20 FL	*- FL
14	1		*FRT RH DOOR HANDLE INNER BASE	Serviceable	224.70 FL	*- FL
15	1		*FRT RH DOOR HANDLE SWITCH	Serviceable	44.80 FL	*- FL
16	1		*FRT DOOR INNER TRIM	Serviceable	1,855.90 FL	*- FL
17	1		*RH CENTER PILLAR OUTER	Repair	343.00 FL	*- FL
18	1		*RH ROCKER PANEL GARNISH	Dented / Distorted	633.30 FL	*633.30 FL
19	1		*REAR RH DOOR	Bent	1,597.40 FL	*1,597.40 FL
20	1		*RER RH DOOR HINGE TOP	Repair	103.10 FL	*- FL
21	1		*REAR RH DOOR HINGE LOWER	Repair	103.10 FL	*- FL
22	1		*REAR RH DOOR CHECKER	Serviceable	233.70 FL	*- FL
23	1		*REAR RH DOOR WINDOW MOULDING (CHROME)	Serviceable	97.90 FL	*- FL
24	1		*REAR RH DOOR FRAME MOULDING (BLACK)	Necessary	83.50 FL	*83.50 FL
25	1		*REAR DOOR WHEATHERSTRIP	Serviceable	217.30 FL	*- FL
26	1		*REAR DOOR LOCK	Repair	595.70 FL	*- FL
27	1		*REAR DOOR GLASS	Serviceable	443.30 FL	*- FL
28	1		*REAR DOOR WINDOW REGULATOR	Serviceable	289.30 FL	*- FL
29	1		*REAR DOOR RUBBER	Serviceable	79.50 FL	*- FL
30	1		*DRIVER SEAT BACKREST CUSHION COVER	Torn	450.00 FL	*450.00 FL
31	1		*DRIVER SEAT BACKREST CUSHION SPONGE	Cracked	100.00 FL	*100.00 FL
32	1		*DRIVER SEAT AIRBAG	Burst	3,039.50 FL	*2,867.40 FL
33	1		*DRIVER SEATBELT	Serviceable	1,050.40 FL	*- FL
34	1		*ROOF LINING	Torn	2,740.50 FL	*1,389.20 FL
35	1		*RH ROOF TOOP AIRBAG	Burst	2,318.00 FL	*2,318.90 FL
36	1		*AIRBAG CONTROL UNIT	Necessary	1,864.90 FL	*1,698.20 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	24,442.50	13,756.20
- List Item Discount on L Items 25.00/25.00% (\$)	6,110.63	3,439.05
Total Parts (\$)	18,331.87	10,317.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To knock & straighten on accident area, to remove & refit RIGHT damage parts	New	1,000.00	700.00
2	To putty & respray on frt rh door, rear rh door, rh center pillar, rh rocker panel garnish, rh roof top pillar	New	1,000.00	900.00
3	To repair rh roof top pillar	New	400.00	200.00
4	To check wiring	New	100.00	20.00
5	To remove & refit FRT RH Door trim, door glass, window regulator, door lock to assist work load.	New	80.00	80.00
6	To remove & refit REAR RH Door trim, door glass, window regulator, door lock to assist work load.	New	80.00	80.00
7	To refit airbag system	New	400.00	250.00
8	To reset airbag control unit	New	200.00	0.00
9	To remove & refit roof lining, inner trim to assist work load	New	200.00	120.00
10	To remove & refit inner seat & upholstery to assist work load	New	150.00	0.00
			Gross Labour Cost (\$)	3,610.00
				2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >