

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22008552/ACY3Q2**Date:** 03/07/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SKZ2293R**Insured Vehicle No :** YQ6556M

Date of Loss: 31/08/2022

Nature of Claim: TP

Claim No: 2022 22006463KC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKZ2293R**

Make & Model: HONDA VEZEL, 1.5 X (A)

Engine No: L15B4027009

Reg. Date: 14/01/2016 (Man. Year: 2015)

Chassis No: RU11107008

Colour: Maroon

Odometer: 316975 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,024.48	5,529.84	1,494.64	21.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,470.00	680.00	31.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,174.48	6,999.84	2,174.64	23.70
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	9,174.48	5,500.00	3,674.48	40.05
+ GST 8.00/8.00% (S\$)	733.96	440.00	293.96	40.05
Nett Amount (S\$)	9,908.44	5,940.00	3,968.44	40.05
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 01/09/2022

Date Inspected: 02/09/2022 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ2293R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	801.70 FL	*801.70 FL
2	1		*FRONT BUMPER LOWER LID GARNISH	Not Necessary	381.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER L/R	N/S Damaged	41.20 FL	*20.60 FL
4	1		*FRONT LH DOOR	Dented	1,080.50 FL	*1,080.50 FL
5	1		*FRONT LH DOOR FRAME BLACK TAPE	Necessary	33.00 FL	*33.00 FL
6	2		*FRONT LH DOOR HINGES (TOP & LOWER)	Not Necessary	97.20 FL	*- FL
7	1		*FRONT LH DOOR INNER PLASTIC SEAL COVER	Not Necessary	35.30 FL	*- FL
8	1		*FRONT LH DOOR OUTER MOULDING	Not Necessary	60.00 FL	*- FL
9	1		*FRONT LH DOOR SIDE MIRROR	Damaged	956.50 FL	*956.50 FL
10	1		*FRONT LH DOOR SIDE MIRROR COVER	Cracked	82.00 FL	*82.00 FL
11	1		*FRONT LH FENDER	Dented	580.00 FL	*580.00 FL
12	1		*FRONT LH FENDER ARCH GARNISH	Cut	220.00 FL	*220.00 FL
13	1		*FRONT LH FENDER INNER SHIELD	Torn	130.00 FL	*130.00 FL
14	1		*FRONT LH HEADLAMP	Cracked	1,784.50 FL	*1,784.50 FL
15	1		*FRONT LH HEADLAMP LOWER BRACKET	Not Necessary	35.00 FL	*- FL
16	1		*FRONT LH KNUCKLE ARM	Not Necessary	390.00 FL	*- FL
17	1		*FRONT LH KNUCKLE ARM BEARING	Damaged	190.00 FL	*190.00 FL
18	1		*FRONT LH LOWER ARM	Bent	371.00 FL	*371.00 FL
19	1		*FRONT LH LOWER ARM BALL JOINT	Not Necessary	98.70 FL	*- FL
20	1		*FRONT LH WHEEL RIM	Cut	650.40 FS	*450.00 FS
21	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
22	1		*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*SET FRONT LH FENDER ARCH GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
24	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS
25	1		*FRONT LH TYRE	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,498.00	6,779.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,473.52	1,249.96
Total Parts (\$\$)	7,024.48	5,529.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS CHECK LIGHTING (TO FR)	New	50.00	30.00
2	TO REMOVE ,REINSTALL FRONT SUSPENSION UNDERCARRIAGE PARTS (TO FR)	New	200.00	150.00
3	TO ROAD TEST DRIVING ,CHECK AND RESETTNG WHEEL ALIGNMENT SYSTEM	New	100.00	80.00
4	TO TRANSFER DOOR GLASS ,REGULATOR GEAR ,MOTOR ,RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	100.00	60.00
5	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	900.00	600.00
6	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	700.00	500.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	50.00
Gross Labour Cost (S\$)			2,150.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >