

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008554/DCY3Q2**Date:** 13/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00092622200

Claimant Vehicle No : SND1883A **Insured Vehicle No :** XE7463R

Date of Loss: 30/08/2022 Nature of Claim: TP Claim No: SNM22D206166/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SND1883A**

Make & Model: MERCEDES-BENZ GLA180, 1.6 (A) Engine No: 27091031908912

Reg. Date: 26/09/2019 (Man. Year: 2019) Chassis No: WDC1569422J657583

Colour: Black Odometer: 57015 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18

Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,006.81	6,115.43	5,891.38	49.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,770.00	1,310.00	42.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,086.81	7,885.43	7,201.38	47.73
Approved Total (Overridden) (\$\$)		6,300.00		
Nett Amount (\$\$)	15,086.81	6,300.00	8,786.81	58.24

INSPECTION

Date of Assignment: 06/09/2022

Date Inspected: 01/09/2022 Inspected At: Bethlehem Auto (HQ)
Blk 5035 Ang Mo Kio Industrial Park 2, #01-371
Singapore 569538

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Sep 2022)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND1883A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR DOOR RH	Dented	2,142.71 FL	*2,082.17 FL
2	1	*REAR DOOR WEATHER STRIP	Serviceable	309.94 FL	*- FL
3	1	*REAR DOOR WINDOW MOULDING	Serviceable	250.03 FL	*- FL
4	1	*REAR DOOR BLACK PLASTIC	Necessary	89.00 FL	*89.00 FL
5	1	*REAR DOOR INNER TRIM BOARD	Not Necessary	1,466.42 FL	*- FL
6	1	*REAR DOOR WINDOW MOTOR	Not Necessary	650.85 FL	*- FL
7	1	*REAR DOOR WINDOW REGULATOR	Not Necessary	752.48 FL	*- FL
8	2	*REAR DOOR HINGE	Not Necessary	214.76 FL	*- FL
9	1	*REAR DOOR LOCK	Not Necessary	379.92 FL	*- FL
10	1	*REAR FENDER RH	Dented	2,584.21 FL	*2,255.00 FL
11	1	*REAR FENDER ARC GARNISH RH	Cut	286.12 FL	*286.12 FL
12	1	*REAR FENDER INNER TRIM RH	Not Necessary	984.69 FL	*- FL
13	1	*REAR BUMPER	Cut	1,300.24 FL	*1,266.00 FL
14	1	*REAR BUMPER SIDE RETAINER RH	Serviceable	91.78 FL	*- FL
15	1	*REAR BUMPER LOWER LID	Cut	703.36 FL	*485.00 FL
16	1	*REAR BUMPER SENSOR	1PCS Damaged/1PCS NotNecessary	487.72 FL	*243.86 FL
17	1	*SET REAR BUMPER SENSOR HOLDER	Serviceable	120.00 FL	*- FL
18	1	*REAR BUMPER SENSOR O-RING	Necessary	10.00 FL	*10.00 FL
19	1	*REAR DOOR EDGE PROTECTOR	Not Necessary	140.00 FS	*- FS
20	1	*SET REAR DOOR INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
21	1	*REAR FENDER SEALANT	Necessary	80.00 FS	*40.00 FS
22	1	*SET REAR FENDER ARC GARNISH CLIPS	Necessary	45.00 FS	*15.00 FS
23	1	*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
24	1	*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
25	1	*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,289.23 6,787.15
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,282.42 671.72

Total Parts (\$\$) 12,006.81 6,115.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,000.00	700.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,000.00	700.00
3	TO APPLY TUFF COAT ON ALL AFFECTED AREAS	New	80.00	40.00
4	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	100.00	40.00
5	TO RNR ALL INTERIOR UPHOLSTERY TO FACILITATE REPAIRS	New	100.00	80.00
6	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
7	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	100.00	0.00
8	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	500.00	150.00
Gross Labour Cost (\$\$)			3,080.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >