

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008565/APA3Q2**Date:** 22/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070172977
Claimant Vehicle No :	SMQ7368A	Insured Vehicle No :	GBF5347L
Date of Loss:	27/08/2022	Nature of Claim:	TP
		Claim No:	9519946522SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ7368A	Engine No:	L13B3940137
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Chassis No:	GK33425645
Reg. Date:	29/11/2019 (Man. Year: 2019)	Odometer:	41712 km
Colour:	Blue		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,477.60	3,755.36	6,722.24	64.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	1,650.00	1,770.00	51.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,897.60	5,405.36	8,492.24	61.11
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	13,897.60	4,300.00	9,597.60	69.06
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		70.00		
Nett Liability (S\$)		5,077.45		
Global Sum Settlement (S\$)		5,000.00		

INSPECTION

Date of Assignment:	30/08/2022	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	30/08/2022 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	801.20 FL	*517.00 FL
2	1		*FRONT BUMPER FOGLAMP COVER GARNISH LH	Deformed	68.30 FL	*68.30 FL
3	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	180.40 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE SIDE GARNISH LH	Deformed	49.40 FL	*49.40 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	263.30 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER	N/S Damaged	36.80 FL	*18.40 FL
7	1		*HEADLAMP	N/S Cracked	3,200.40 FL	*1,600.20 FL
8	1		*HEADLAMP LOWER BRACKET	N/S Cracked	76.40 FL	*38.20 FL
9	1		*CENTER GRILLE	Cracked	352.20 FL	*352.20 FL
10	1		*CENTER GRILLE LOGO	Necessary	29.40 FL	*29.40 FL
11	1		*CENTER GRILLE UPPER CHROME	Not Necessary	224.30 FL	*- FL
12	1		*CENTER GRILLE LOWER CHROME	Cut	265.40 FL	*265.40 FL
13	1		*CENTER GRILLE BRACKET	Not Necessary	37.40 FL	*- FL
14	1		*CENTER GRILLE INNER GARNISH	Not Necessary	122.40 FL	*- FL
15	1		*FRONT FENDER LH	Repair	435.20 FL	*- FL
16	1		*FRONT FENDER QUARTER GLASS LH	Not Necessary	155.20 FL	*- FL
17	2		*FRONT FENDER COWLING	Not Necessary	250.60 FL	*- FL
18	1		*FRONT WHEEL HOUSE EXTEND PANEL LH	Not Necessary	51.50 FL	*- FL
19	1		*BONNET	Dented	550.20 FL	*550.20 FL
20	1		*BONNET INSULATOR	Crumpled	215.40 FL	*215.40 FL
21	1		*BONNET LOCK	Not Necessary	97.70 FL	*- FL
22	2		*BONNET STOPPER	Not Necessary	34.40 FL	*- FL
23	1		*BONNET TOP GARNISH LH	Not Necessary	137.20 FL	*- FL
24	1		*BONNET HINGE	N/S Bent	78.80 FL	*39.40 FL
25	1		*BONNET INNER RUBBER	N/S Cut	118.40 FL	*59.20 FL
26	1		*FRONT SUPPORT PANEL	Dented	455.20 FL	*455.20 FL
27	1		*FRONT SUPPORT LOWER APRON PANEL	Dented	196.50 FL	*196.50 FL
28	1		*AIR DUCT	Not Necessary	79.40 FL	*- FL
29	1		*AIR CLEANER FLEXIBLE DUCT	Not Necessary	94.50 FL	*- FL
30	1		*AIR RESONATOR BOX	Not Necessary	317.10 FL	*- FL
31	1		*FRONT WINDSCREEN SIDE MOULDING	N/S Damaged	204.60 FL	*102.30 FL
32	1		*AIR CON CONDENSER	Not Necessary	704.20 FL	*- FL
33	4		*AIR CON CONDENSER MOUNTING RUBBER	Not Necessary	117.60 FL	*- FL
34	2		*AIR CON CONDENSER BRACKET	Not Necessary	58.80 FL	*- FL
35	1		*AIR CON CONDENSER SIDE GARNISH	Not Necessary	27.40 FL	*- FL
36	1		*RADIATOR	Not Necessary	1,540.80 FL	*- FL
37	2		*RADIATOR RUBBER MOUNTING	Not Necessary	78.80 FL	*- FL
38	1		*BATTERY TRAY	Not Necessary	78.30 FL	*- FL
39	2		*BATTERY BRACKET	Not Necessary	99.40 FL	*- FL
40	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
41	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
42	1		*SET FRONT BUMPER FOGLAMP COVER GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
43	1		*SET FRONT BUMPER LOWER GRILLE SIDE GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
44	1		*BONNET SEALANT	Not Necessary	150.00 FS	*- FS
45	1		*SET BONNET AIR GUARD GARNISH CLIP	Not Necessary	30.00 FS	*- FS
46	1		*SET CENTER GRILLE CLIP	Necessary	30.00 FS	*20.00 FS
47	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	150.00 FS	*- FS
48	1		*FRONT SUPPORT LOWER APRON PANEL SEALANT	Not Necessary	120.00 FS	*- FS
49	1		*BATTERY	Not Necessary	250.00 FS	*- FS
50	1		*COOLANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,854.50	4,666.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,376.90	911.34
Total Parts (\$\$)	10,477.60	3,755.36

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,400.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	700.00
3	WIRING CHECK	New	180.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
6	REFOCUS HEADLAMP BEAM	New	60.00	0.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			3,420.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >