

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008567/APA3Q2**Date:** 04/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220029044
Claimant Vehicle No :	SNF3600B	Insured Vehicle No :	GBL7710B
Date of Loss:	14/08/2022	Nature of Claim:	TP
		Claim No:	5993731602SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF3600B	Engine No:	2ARF429015
Make & Model:	TOYOTA LEXUS, 2.5 ES250 AUTO (A)	Chassis No:	JTHBJ1GG402102824
Reg. Date:	18/07/2017 (Man. Year: 2017)	Odometer:	132554 km
Colour:	Black		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	245/40 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,006.98	4,373.67	5,633.31	56.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	1,620.00	2,060.00	55.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,686.98	5,993.67	7,693.31	56.21
Approved Total (Overridden) (S\$)		4,800.00		
Nett Amount (S\$)	13,686.98	4,800.00	8,886.98	64.93
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
		(S\$)	5,300.00	
Liabe Amount (50.00%) (S\$)		2,650.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,657.45		

INSPECTION

Date of Assignment:	30/08/2022	
Date Inspected:	30/08/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,218.00 FL	*1,015.00 FL
2	1		*REAR BUMPER SIDE RETAINER (FRONT)	N/S Cracked	270.40 FL	*135.20 FL
3	1		*REAR BUMPER SIDE RETAINER (REAR)	N/S Cracked	341.60 FL	*170.80 FL
4	1		*REAR BUMPER SPONGE	Cracked	159.50 FL	*159.50 FL
5	2		*REAR FENDER INNER COWLING	Not Necessary	569.80 FL	*- FL
6	1		*TAIL LAMP	Cut	672.90 FL	*672.90 FL
7	1		*TAIL LAMP LOWER BRACKET	Not Necessary	85.70 FL	*- FL
8	1		*REAR FENDER LH	Repair	2,316.00 FL	*- FL
9	1		*REAR FENDER AIR VENT LH	Not Necessary	86.70 FL	*- FL
10	1		*REAR FENDER AIR VENT COVER GARNISH LH	Deformed	89.00 FL	*89.00 FL
11	1		*REAR WINDSCREEN MOULDING	Not Necessary	187.00 FL	*- FL
12	1		*REAR BLINDSPOT SENSOR LH	Cracked	1,683.90 FL	*1,683.90 FL
13	1		*REAR BLINDSPOT SENSOR WIRE HARNESS	Not Necessary	461.70 FL	*- FL
14	2		*REVERSE SENSOR	Not Necessary	795.60 FL	*- FL
15	4		*REVERSE SENSOR HOLDER	Not Necessary	114.40 FL	*- FL
16	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
17	1		*REAR BUMPER DIFFUSER (SPECAIL TYPE)	Cracked	1,500.00 FS	*800.00 FS
18	1		*REAR FENDER SEALANT	Not Necessary	150.00 FS	*- FS
19	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	50.00 FS	*- FS
20	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
21	1		*SET TAIL LAMP CLIP	Necessary	30.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,912.20	4,766.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	905.22	392.63
Total Parts (\$\$)	10,006.98	4,373.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	600.00
3	TUFF COAT	New	100.00	40.00
4	WIRING BULB CHECKING	New	120.00	30.00
5	REMOVE & REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
6	RESET BLIND STOP SYSTEM	New	800.00	400.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			3,680.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >