

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22008573/UQY3Q2**Date:** 28/10/2022**REFERENCE**

Insured/Claimant: Muhammad Syafiq Bin Azman Policy No: SP2002390510-01
Date of Loss: 26/08/2022 Nature of Claim: OD Claim No: 202222006367JK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT7447B**
Make & Model: VOLKSWAGEN POLO, 1.4 (A) Engine No: CGG337922
Reg. Date: 26/07/2010 (Man. Year: 2010) Chassis No: WVVWZZZ6RZAU060030
Colour: Multi-colour Odometer: 148946 km
Engine Capacity: 1390 cc
Market Value/New Car Price: S\$60,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Excellent Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,315.20	4,372.50	942.70	17.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	720.00	160.00	18.18
Paintwork Labour	800.00	700.00	100.00	12.50
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,995.20	5,792.50	1,202.70	17.19
Approved Total (Overridden) (S\$)		4,050.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	6,395.20	3,450.00	2,945.20	46.05
+ GST 7.00/7.00% (S\$)	447.66	241.50	206.16	46.05
Nett Amount (S\$)	6,842.86	3,691.50	3,151.36	46.05

INSPECTION

Date of Assignment: 02/09/2022 Present Location: Tan Lim Motor Pte Ltd (Defu)
Date Inspected: 02/09/2022 Inspected At: Tan Lim Motor Pte Ltd (Defu)
Estimated Period of Repair: 5.0 days 1 Defu Lane 6
Singapore 539365

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Oct 2022)
Parts:	144	VOLKSWAGEN POLO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT7447B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*front bumper	Distorted	650.00 F	*650.00 F
2	8		*front bumper clips	Necessary	12.00 F	*12.00 F
3	2		*front bumper side retainer	Bent / Cracked	170.00 F	*170.00 F
4	1		*front bumper center grille	Torn	110.00 F	*110.00 F
5	2		*front bumper side grille	Cut / Missing	90.00 F	*90.00 F
6	2		*headlamp	Broken	440.00 F	*440.00 F
7	1		*bonnet	Buckled	550.00 F	*550.00 F
8	1		*front bumper lower lip (CUT)	Not Consistent With The Impact	65.00 F	*- F
9	1		*front grille assy	Cracked	265.00 F	*265.00 F
10	1		*front grille emblem	Cracked	70.00 F	*70.00 F
11	1		*front grille R emblem	Not Insured	25.00 F	*- F
12	2		*bonnet hinge	Repair	140.00 F	*- F
13	1		*bonnet open lever	Not Necessary	45.00 F	*- F
14	1		*bonnet lock	Twisted	120.00 F	*120.00 F
15	1		*front fender	N/S Buckled / O/S Repair	600.00 F	*300.00 F
16	2		*front fender inner cowling	Not Necessary	220.00 F	*- F
17	8		*front fender inner cowling clips	Not Necessary	12.00 F	*- F
18	2		*front fender emblem	Not Insured	50.00 F	*- F
19	1		*front support panel	Cracked	500.00 F	*500.00 F
20	1		*aircon condenser	Bent / Punctured	275.00 F	*275.00 F
21	2		*aircon air guide	Torn	30.00 F	*30.00 F
22	1		*radiator assy	Bent / Punctured	240.00 F	*240.00 F
23	2		*headlamp panel	Buckled	80.00 F	*80.00 F
Supplementary #1						
24	1		*main fuse socket	Damaged	73.00 F	*73.00 F

F=Franchise part.

Sub Total (\$\$)	4,832.00	3,975.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	483.20	397.50
Total Parts (\$\$)	5,315.20	4,372.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Putty and spray painting of the affected portion.	New	800.00	700.00
Labour Items				
2	To check electrical lighting concerned.	New	60.00	20.00
3	To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	New	120.00	100.00
4	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	700.00	600.00
Gross Labour Cost (\$\$)			1,680.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >