

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIS22008574/KPA3Q2**Date:** 20/03/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001028395
<b>Claimant Vehicle No :</b>	SGT9363E	<b>Insured Vehicle No :</b>	GBL7371X
Date of Loss:	26/08/2022	Nature of Claim:	TP
		Claim No:	202222006652

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SGT9363E</b>	Engine No:	LEB5640916
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71100016
Reg. Date:	18/11/2019 (Man. Year: 2019)	Odometer:	116429 km
Colour:	Metallic Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,776.34	2,895.40	5,880.94	67.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,420.00	1,280.00	47.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,476.34</b>	<b>4,315.40</b>	<b>7,160.94</b>	<b>62.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,450.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,476.34</b>	<b>3,450.00</b>	<b>8,026.34</b>	<b>69.94</b>
<b>+ Car Rental (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,052.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,050.00</b>		

**INSPECTION**

Date of Assignment:	29/08/2022	TSR AUTOMOTIVE PTE LTD (HQ) 160 SIN MING DRIVE, #06-01 SIN MING AUTOCITY Singapore 575722
Date Inspected:	29/08/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2023)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT9363E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,385.60 FL	*1,245.30 FL
2	1		*TAILGATE OUTER CHROME	Mtg Cracked	480.00 FL	*264.80 FL
3	1		*TAILGATE CENTER LOGO	Necessary	58.00 FL	*58.00 FL
4	1		*TAILGATE FREED EMBLEM	Necessary	55.00 FL	*55.00 FL
5	1		*TAILGATE WEATHERSTRIP	Dented / Distorted	168.00 FL	*168.00 FL
6	2		*TAILGATE LAMPS	Serviceable	1,160.00 FL	*- FL
7	1		*TAILGATE TRIM BOARD	Mtg Cracked	485.00 FL	*391.70 FL
8	1		*TAILGATE WIPER MOTOR	Serviceable	449.00 FL	*- FL
9	1		*TAILGATE LOCK	Dented	480.00 FL	*186.20 FL
10	1		*TAILGATE LOCK LOWER SENSOR	Serviceable	339.00 FL	*- FL
11	1		*TAILGATE LOCK SWITCH	Serviceable	228.00 FL	*- FL
12	2		*TAILLAMPS	Serviceable	1,256.00 FL	*- FL
13	2		*TAILLAMP PANELS (NPA)	Repair	0.00 FL	*- FL
14	2		*TAILLAMP LOWER BRACKETS	Repair	220.00 FL	*- FL
15	1		*REAR BUMPER	Buckled / Dented	895.00 FL	*829.00 FL
16	2		*REAR BUMPER SIDE RETAINERS	Serviceable	180.00 FL	*- FL
17	1		*END PANEL	Repair	580.00 FL	*- FL
18	1		*END PANEL TOP GARNISH	Mtg Cracked	332.00 FL	*115.00 FL
19	1		*END PANEL TOP LATCH	Repair	62.00 FL	*- FL
20	10		*REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
21	1		*SET REVERSE CAMERA	Serviceable	500.00 FS	*- FS
22	1		*SET REVERSE SENSORS	Shorted	300.00 FS	*200.00 FS
					Sub Total (\$\$)	9,657.60 3,558.00
					- List Item Discount on L Items 10.00/20.00% (\$\$)	881.26 662.60
					Total Parts (\$\$)	8,776.34 2,895.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REPAIR ,REPLACE ACCIDENT AFFECTED,AFFECTED AREA	New	800.00	500.00
2	TRANSFER TAILGATE PARTS TO ANOTHER TAILGATE	New	140.00	60.00
3	TO REMOVE REFIX REAR W/SCREEN	New	140.00	120.00
4	TO REPLACE SENSORS ,REVERSE CAMERA CHECK REAR WIRING SYSTEM ETC	New	150.00	50.00
5	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA INNER AND OUTER	New	800.00	600.00
6	TO DO COMPUTER SETTING ,DIGNOSE DELETE FAULT CODE AFTER REPAIR	New	250.00	0.00
7	TO DO SEALANT ,SEAL GAP ,WATERPROOFING ON REAR CUTTING WELDING AREA	New	150.00	0.00
8	TO DO ANTI RUST	New	90.00	30.00
9	TO REMOVE REFIX REPLACE GARNISH ,SIDE TRIMS ,UPHOLSTERY ETC	New	180.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,700.00</b>	<b>1,420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >