

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA22008576/EQY3E2**Date:** 17/02/2023**REFERENCE**

Insured/Claimant: SIM SHAO KWAN, MALCOLM

Policy No: MP307194

Date of Loss: 22/08/2022

Nature of Claim: OD

Claim No: MPC03641/ANA

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLN1887K**

Make & Model: RENAULT MEGANE, 1.5 SEDAN DCI EU6 (A)

Engine No: K9KG657R009670

Reg. Date: 25/04/2017 (Man. Year: 2017)

Chassis No: VF1RFB00357527657

Colour: White

Odometer: 47213 km

Engine Capacity: 1461 cc

Market Value/New Car Price: S\$62,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R17

Rear Tyre Size: 205/50 R17

Front Left Side: Continental 4 mm

Rear Left Side: Continental 4 mm

Front Right Side: Continental 4 mm

Rear Right Side: Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,368.40	9,438.30	7,930.10	45.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,890.00	10,715.00	2,175.00	16.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,258.40	20,153.30	10,105.10	33.40
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	29,658.40	19,553.30	10,105.10	34.07
+ GST 8.00/8.00% (S\$)	2,372.67	1,564.26	808.41	34.07
Nett Amount (S\$)	32,031.07	21,117.56	10,913.51	34.07

INSPECTION

Date of Assignment: 02/09/2022

Date Inspected: 12/09/2022 Inspected At:

Wearnes Automotive Pte Ltd (Alexandra Road)

249 Alexandra Road

Singapore 159935

Estimated Period of Repair: 13.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Feb 2023)
Parts:	143	RENAULT MEGANE 1.5 SEDAN DCI EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN1887K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR FRT LH M4S	Repair	2,027.40 FS	*- FS
2	1		*DOOR REAR LH M4S	Dented	2,027.40 FS	*1,824.66 FS
3	1		*WINDOW MOULDING FRT	Not Necessary	344.50 FS	*- FS
4	1		*WINDOW MOULDING REAR	Cracked	346.60 FS	*311.94 FS
5	1		*WINDOW SEAL FRT LH O	Not Necessary	249.60 FS	*- FS
6	1		*WINDOW SEAL RR LH OU	Not Necessary	272.20 FS	*- FS
7	1		*MLDG-RR PLR, FR LH DO	Necessary	110.50 FS	*99.45 FS
8	1		*MLDG-RR LH DOOR FR P	Necessary	469.90 FS	*422.91 FS
9	1		*C PILLAR DOOR TOP	Cut	56.10 FS	*50.49 FS
10	1		*WHEEL ARCH REAR LH M	Not Necessary	277.60 FS	*- FS
11	1		*MUDGUARD-RR LH	Not Necessary	84.00 FS	*- FS
12	1		*TAILAMP INNER SUPPOR	Not Necessary	532.80 FS	*- FS
13	1		*FENDER REAR LH M4S	Dented	2,130.90 FS	*1,917.81 FS
14	1		*NOISE DEADENING PAD (4PCS)	Necessary (2Pcs Only)	2,427.60 FS	*1,092.42 FS
15	1		*WING MIRROR ASSY LH	Not Necessary	810.40 FS	*- FS
16	1		*WING MIRROR COVER LO	Not Necessary	158.00 FS	*- FS
17	1		*WING MIRROR COVER TO	Not Necessary	165.60 FS	*- FS
18	1		*BUMPER REAR M4S	Broken	952.70 FS	*857.43 FS
19	1		*BUMPER REAR INNER SI	Not Necessary	231.30 FS	*- FS
20	1		*BUMPER REAR SIDE SUP	Broken	350.80 FS	*315.72 FS
21	1		*BUMPER REAR OUTER SI	Broken	241.90 FS	*217.71 FS
22	1		*TOW COVER RR M4S	Not Necessary	94.00 FS	*- FS
23	1		*BUMPER PAD LOWER M4S	Not Necessary	429.30 FS	*- FS
24	1		*ALLOY RIM 7 XJ 1 M4S	Cut	628.50 FS	*565.65 FS
25	1		*TYRE PRESSURE SENSOR	Necessary	121.90 FS	*109.71 FS
26	1		*WDW-MOBILE, RR LH DO	Cut	490.50 FS	*441.45 FS
27	1		*PRIMER	Necessary	204.70 FS	*184.23 FS
28	2		*WINDSCREEN SEALANT	Necessary	268.00 FS	*241.20 FS
29	1		*WINDSCREEN REAR M4S	Necessary	781.80 FS	*703.62 FS
30	10		*RIVET SILVER, REAR B	Necessary	18.90 FS	*18.90 FS
31	10		*RIVET BLACK, BUMPER	Necessary	63.00 FS	*63.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **17,368.40** **9,438.30**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE LHF DOOR, LHR DOOR, LHR FENDER, REAR BUMPER, LHS WING MIRROR COVER, B PILLAR DOOR TRIMS, BRACKETS, CLIPS, ETC	New	4,400.00	3,575.00
2	TO BLEND AND SPRAY PAINT ON LHF DOOR, LHR DOOR, LHR FENDER, LHR FENDER INNER PANEL, LHS ROOF TOP SIDE PANEL, REAR BUMPER, LHS WING MIRROR COVER, ETC	New	3,250.00	3,250.00
3	TO TRANSFER LHF DOOR AND LHR DOOR MECHANISM	New	500.00	250.00
4	TO REPLACE LHR DOOR GLASS	New	550.00	550.00
5	TO INSTALL LHR DOOR GLASS SOLAR FILM	New	280.00	280.00
6	TO REPLACE REAR WINDSCREEN	New	550.00	550.00
7	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	280.00	280.00
8	TO REMOVE AND INSTALL INTERIOR PARTS	New	1,650.00	1,100.00
9	TO REMOVE AND INSTALL REAR BOO COMPARTMENT PARTS	New	1,100.00	550.00
10	TO REPLACE LHR RIM	New	50.00	50.00
11	WHEEL ALIGNMENT	New	280.00	280.00
Gross Labour Cost (\$\$)			12,890.00	10,715.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >