

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22008577/Gvy3e2
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55		Date:	15/09/2022
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YQ 222R	Veh. Inspected		YQ 4760C
	Policy No.		Coverage (\$)		0.00
	Claim No.	22/22/22/VC05/026212	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		02/09/2022
2.	Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI FUSO FM65FM6RDEA	c.c		7545
	Engine No.	HIDDEN	Year of Reg.		2021
	Chassis No.	FM65FMA40103	Colour		WHITE
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	11 R22.5	DUNLOP		6 mm
	L/H Front Tyre	11 R22.5	DUNLOP		6 mm
	R/H Rear Tyre	11 R22.5 (D)	DUNLOP		6/6 mm
	L/H Rear Tyre	11 R22.5 (D)	DUNLOP		6/6 mm
4.	Description of Damages				
	THE VEHICLE SUSPORTION.	STAINED DAMAGES AT THE FRONT AND REAR			
5.	General Information				
	Accident Date	25/08/2022	Inspect Date /	Time	05/09/2022 ( 12:30 PM )
	Survey held at	DERRICK MOTOR WORKS			
		BLK 9002 #01-72 TAMPINES ST 93 SINGAPORE 528836			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22008577/Gvy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor**