



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4669U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER ASSY	TO REPAIR SEE LABOUR	503.04	-
1	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	992.04	-
1	REAR BUMPER BRACKET LH	NOT NECESSARY	94.80	-
1	REAR BUMPER CENTRE MOULDING	NOT NECESSARY	654.96	-
	LESS 25% DISCOUNT		-566.71	-
			1,700.13	-
SPECIAL NETT ITEMS				
1	PETROL STICKER (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
			80.00	30.00
LABOUR				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER ASSY AND REAR FENDER LH.		1,100.00	280.00
	SPRAY PAINT.		600.00	500.00
	REMOVE / REFIX REVERSE SENSOR.		50.00	40.00
	CHECK WIRING.	NOT NECESSARY	50.00	-
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX UPHOLSTERY REAR.	NOT NECESSARY	120.00	-
			1,970.00	820.00
GRAND TOTAL			3,750.13	850.00

RECOMMENDED COST OF REPAIRS (CONFIRMED)			850.00
--	--	--	---------------

Report Ref No. NS/INC22008581/Gvce2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.