



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3185U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRT FENDER RH	BUCKLED	588.80	588.80
1	FRT FENDER BLUE-DRIVE RH	NECESSARY	26.60	26.60
1	DAYLIGHT RH	NOT NECESSARY	642.50	-
1	DAYLIGHT GRILLE RH	CUT	93.45	93.45
1	FRT BUMPER	TO REPAIR SEE LABOUR	481.10	-
1	FRT BUMPER UPPER MOULDING	NOT NECESSARY	368.50	-
1	FRT BUMPER SIDE BRACKET RH	NOT NECESSARY	35.00	-
10	FRT BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	FRT WHEEL CAP RH	SCRATCHED	346.40	346.40
1	HEADLAMP RH	SCRATCHED	2,110.30	2,110.30
1	ROCKER PANEL GARNISH RH	NOT NECESSARY	290.00	-
	LESS 20% DISCOUNT		-1,000.93	-633.11
			4,003.72	2,532.44
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT BUMPER.		800.00	350.00
	SPRAY PAINTING CHARGE.		900.00	500.00
	CHECK LIGHTINGS.		60.00	30.00
	TUFF KOTE.		60.00	40.00
	WHEEL ALIGNMENT.		120.00	60.00
			1,940.00	980.00
<b>GRAND TOTAL</b>			<b>5,943.72</b>	<b>3,512.44</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>2,800.00</b>

Report Ref No. NS/INC22008583/Gqcm4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.