

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD7308/B

Date: 26.08.2022

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER <i>MC</i>			\$459.40
10	REAR BUMPER CLIPS <i>MC</i>			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY <i>Cut</i>			\$451.25
1	REAR BUMPER REINFORCEMENT X NN			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH <i>X NN</i>			\$138.10
1	REAR BUMPER SIDE BRACKET LH <i>Cut</i>			\$55.80
1	REAR BUMPER LOWER CTR MOULDING <i>BR</i>			\$155.00
1	REAR BUMPER CENTRE UNDER COVER <i>X NN</i>			\$225.00
1	REAR BUMPER SIDE UNDER COVER LH <i>TD</i>			\$108.00
1	REAR BUMPER REFLECTOR LAMP LH <i>Cut</i>			\$41.45
SUB TOTAL				\$2,050.80
LESS 20%				\$410.16
DISCOUNTED TOTAL				\$1,640.64
REAR BUMPER RUBBER MAT <i>MC</i>				\$50.00
REAR NUMBER PLATE WITH TRIM COVER <i>X NN</i>				\$55.00
REAR BUMPER REVERSE SENSOR <i>X</i>				\$180.00
				\$285.00
Labour Charge				
PANEL BEATING				\$400.00
SPRAY PAINTING CHARGE				\$300.00
REMOVE/REFIX REVERSE SENSOR				\$80.00
TOTAL LABOUR				\$780.00
ESTIMATE TOTAL				\$2,705.64
				1350

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.
4/5
Kmo Q: p
29/8/22
vpm

LKK Auto Consult is hereby notified
the Repairer of the following:

- To resurvey before any repair work commencing
- To display damaged parts for resurvey
- Parts prices are subject to resurvey
- Third party survey is done on a "no-haggle" basis
- No illegal modification of parts
- Supplementary items are subject to final approval
- Is subject to final approval by the insurance company

Acknowledged by Repairer
Signature: _____