



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 4767T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR LH	BUCKLED	2,442.50	1,680.00
1	REAR DOOR INNERTRIM LH	NOT NECESSARY	287.50	-
1	REAR DOOR WEATHERSTRIP	NOT NECESSARY	225.00	-
1	REAR WINDSCREEN LH	SMASHED	380.00	380.00
1	TAILLAMP LH	CRACKED	535.00	385.00
1	"FLORINO" EMBLEM	NECESSARY	197.50	60.00
1	"ECOJET" EMBLEM	NECESSARY	167.50	40.00
1	REAR BUMPER	DEFORMED	670.00	670.00
10	REAR BUMPER CLIP - \$10/PC	NECESSARY	100.00	30.00
1	REAR BUMPER RETAINER LH	BENT	217.50	58.00
1	REAR BUMPER RETAINER RH	NOT NECESSARY	217.50	-
1	REAR BUMPER REINFORCEMENT	CRACKED	340.00	340.00
1	END PANEL CENTRE	NOT NECESSARY	987.50	-
1	END PANEL LH	NOT NECESSARY	1,390.00	-
1	REAR FENDER TOP LH	TO REPAIR SEE LABOUR	1,150.00	-
1	REAR FENDER INNERSHIELD LH	NOT NECESSARY	322.50	-
	LESS 10% DISCOUNT		-963.00	-364.30
			8,667.00	3,278.70
<u>SPECIAL NETT ITEMS</u>				
1	"KIM SOON LEE" DECAL (SN)	NECESSARY	200.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	40.00
1	SPEED LIMIT "70KM/ HR" DECAL (SN)	NECESSARY	60.00	10.00
1	REAR NUMBER PLATE W/ HOLDER (SN)	SCRATCHED	90.00	40.00
1	"WWW.KIMSOONLEE.COM" DECAL (SN)	NECESSARY	200.00	30.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
1	REAR WIPER (SN) (ADDITIONAL)	DAMAGED	280.00	20.00
1	REAR WIPER MOTOR (SN) (ADDITIONAL)	NOT NECESSARY	400.00	-
1	COMPANY LOGO DECAL (SN) (ADDITIONAL)	NECESSARY	250.00	50.00
1	"ENQUIRY@KIMSOONLEE.COM" DECAL (SN) (ADDITIONAL)	NECESSARY	200.00	30.00

Report Ref No. CS/INC22008590/Gny3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	"TEL: 6741 2222" DECAL (SN) (ADDITIONAL)	NECESSARY	180.00	20.00
			2,160.00	290.00
	LABOUR			
	TO REMOVE, REPAIR & INSTALL ALL ACCIDENT AFF. PORTIONS. INCLUSIVE OF THE REPAIR OF REAR FENDER TOP LH.		1,200.00	600.00
	TO REMOVE & INSTALL REAR WINDSCREEN.		200.00	100.00
	TO REMOVE & INSTALL REVERSE SENSOR.		250.00	40.00
	TO CHECK ENGINE WARNING LIGHT (ABS, ECU, & ETC.)	NOT NECESSARY	220.00	-
	TO CHECK ALL NECESSARY WIRING.		160.00	30.00
	TO CHECK CHASSIS ALIGNMENT.	NOT NECESSARY	170.00	-
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	90.00	-
	TO CHECK UNDERCARRIAGE.	NOT NECESSARY	180.00	-
	TO PUTTY & RESPRAY ALL ACCIDENT AFF. PORTIONS.		1,500.00	500.00
	TO APPLY ANTI-RUST COATING ON ALL ACCIDENT AFF. PORTIONS.	NOT NECESSARY	170.00	-
	TO INSTALL ALL 5 DECALS (ADDITIONAL).		200.00	100.00
		4,340.00	1,370.00	
GRAND TOTAL			15,167.00	4,938.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,950.00

Report Ref No. CS/INC22008590/Gny3m4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.