

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008591/DCY3Q2**Date:** 28/11/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00041832201

**Claimant Vehicle
No :** SMR4602M**Insured Vehicle
No :** GBJ4474M

Date of Loss: 30/08/2022

Nature of Claim: TP

Claim
No: SNM22D206180/C02/TAYHP**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMR4602M**

Make & Model: KIA CERATO, 1.6 (A)

Engine No: G4FGKH739227

Reg. Date: 08/01/2020 (Man. Year: 2019)

Chassis No: KNAF3416ML5059788

Colour: Grey

Odometer: 73038 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,863.42	5,446.94	15,416.48	73.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,290.00	1,820.00	5,470.00	75.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	28,153.42	7,266.94	20,886.48	74.19
Approved Total (Overridden) (\$\$)		5,800.00		
(\$\$)	28,153.42	5,800.00	22,353.42	79.40
+ GST 7.00/7.00% (\$\$)	1,970.74	406.00	1,564.74	79.40
Nett Amount (\$\$)	30,124.16	6,206.00	23,918.16	79.40

INSPECTION

Date of Assignment: 02/09/2022

Date Inspected: 02/09/2022 Inspected At:

C.s Ong Auto Pte Ltd (HQ)
10 ANG MO KIO INDUSTRIAL PARK 2A, #02-16
AMK AUTOPOINT
Singapore 56804

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2022)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR4602M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP RH	Not Necessary	899.00 FL	*- FL
2	1		*TAIL LAMP PANEL RH	Not Necessary	996.00 FL	*- FL
3	1		*TAIL LAMP LOWER BRACKET RH	Not Necessary	318.00 FL	*- FL
4	1		*REAR BUMPER	Mtg Cracked / Bent	980.00 FL	*688.00 FL
5	2		*REAR BUMPER SIDE RETAINER L+R	Serviceable	190.00 FL	*- FL
6	1		*REAR FENDER RH	Dented	2,189.00 FL	*1,233.00 FL
7	1		*REAR FENDER INNER TRIM RH	Not Necessary	679.00 FL	*- FL
8	1		*REAR FENDER INNER SHIELD RH	Not Necessary	329.40 FL	*- FL
9	1		*REAR WINDSCREEN MOULDING	Necessary	398.00 FL	*112.00 FL
10	1		*REAR WHEEL BEARING & HUB ASSY RH	Damaged	582.00 FL	*378.00 FL
11	1		*REAR ABSORBER RH	Distorted	849.00 FL	*286.00 FL
12	1		*REAR AXLE BEAM	Not Necessary	2,984.00 FL	*- FL
13	1		*REAR DOOR RH	Dented	1,790.00 FL	*1,477.00 FL
14	1		*REAR DOOR WEATHER STRIP OUTER RH	Serviceable	319.00 FL	*- FL
15	1		*REAR DOOR LOCK RH	Not Necessary	412.00 FL	*- FL
16	1		*REAR DOOR WINDOW MOULDING RH	Serviceable	199.00 FL	*- FL
17	1		*REAR DOOR BLACK PLASTIC RH	Necessary	142.20 FS	*80.00 FS
18	1		*REAR DOOR REGULATOR RH	Mtg Cracked	536.00 FL	*422.30 FL
19	1		*REAR DOOR REGULATOR MOTOR RH	Not Necessary	726.00 FL	*- FL
20	1		*REAR DOOR DOOR HANDLE RH	Cut	291.00 FL	*215.00 FL
21	1		*REAR DOOR DOOR HANDLE BASE RH	Not Necessary	182.00 FL	*- FL
22	1		*FRONT DOOR RH	Not Necessary	1,692.00 FL	*- FL
23	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	319.00 FL	*- FL
24	1		*FRONT DOOR BLACK PLASTIC RH	Not Necessary	158.00 FL	*- FL
25	1		*ROCKER PANEL RH	Repair	878.40 FL	*- FL
26	1		*REAR DOOR INNER TRIM BOARD RH	Mtg Broken	850.00 FL	*485.30 FL
27	1		*FENDER SEALANT	Necessary	80.00 FS	*40.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
29	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
30	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
31	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
32	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
34	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
35	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*SPORT RIM	Cut	2,000.00 FS	*500.00 FS
37	1		*TYRE	Serviceable	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,838.00	5,976.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,974.58	529.66
Total Parts (\$\$)	20,863.42	5,446.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	400.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	700.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	400.00	120.00
6	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	New	250.00	60.00
7	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	120.00
8	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	60.00
9	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
11	TO RNR REVERSE SENSOR TO FACILITATE REPAIRS	New	120.00	40.00
Gross Labour Cost (S\$)			7,290.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >