

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008597/UNY3Q2**Date:** 19/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00043112201

Claimant Vehicle No : SJK4115A **Insured Vehicle No :** GBL2393R

Date of Loss: 26/08/2022 Nature of Claim: TP Claim No: SNM22D206068/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJK4115A**

Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZX811652

Reg. Date: 17/10/2008 (Man. Year: 2008) Chassis No: MR053HY9305083047

Colour: Black Odometer: 272335 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Wonder 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Wonder 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,608.00	3,557.80	2,050.20	36.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	2,710.00	1,360.00	33.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,678.00	6,267.80	3,410.20	35.24
Approved Total (Overridden) (\$\$)		5,000.00		
Nett Amount (\$\$)	9,678.00	5,000.00	4,678.00	48.34

INSPECTION

Date of Assignment: 02/09/2022

Date Inspected: 02/09/2022 Inspected At: 2020 Garage Engineering LLP (Ubi) (HQ)
51 Ubi Ave 1 #01-21 Paya Ubi Industrial Park
Singapore 408933

Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2022)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK4115A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Distorted	575.00 FL	*575.00 FL
2	2		*BOOT LID STOPPER	Not Necessary	38.00 FL	*- FL
3	1		*BOOT LID OUTER MOULDING	Bent	190.00 FL	*190.00 FL
4	1		*BOOT LID LOGO	Necessary	70.00 FL	*70.00 FL
5	1		*BOOT LID EMBLEM VIOS	Necessary	65.00 FL	*65.00 FL
6	1		*BOOT LID EMBLEM E	Necessary	55.00 FL	*55.00 FL
7	1		*BOOT LID TOP LOCK	Twisted	155.00 FL	*155.00 FL
8	1		*BOOT LID LOWER LOCK	Not Necessary	25.00 FL	*- FL
9	1		*BOOT LID WEATHERSTRIP	Twisted	205.00 FL	*205.00 FL
10	2		*BOOT LID HINGE	Repair	140.00 FL	*- FL
11	1		*REAR BUMPER	Distorted	495.00 FL	*415.00 FL
12	2		*REAR BUMPER BRACKET	Not Necessary	190.00 FL	*- FL
13	1		*REAR BUMPER REFLECTOR	O/S Cracked	250.00 FL	*125.00 FL
14	2		*REAR BUMPER SIDE RETAINER (FRONT)	Bent	210.00 FL	*210.00 FL
15	2		*REAR BUMPER SIDE RETAINER (REAR)	Bent	110.00 FL	*110.00 FL
16	2		*TAIL LAMP	Cracked	900.00 FL	*710.20 FL
17	2		*REAR FENDER INNER COWLING	Not Necessary	350.00 FL	*- FL
18	2		*REAR FENDER INNER TRIM	Not Necessary	590.00 FL	*- FL
19	1		*REAR END PANEL	Badly Dented	496.00 FL	*496.00 FL
20	1		*REAR END PANEL TOP GARNISH	Distorted	230.00 FL	*184.20 FL
21	1		*REAR FLOOR PANEL TOP BOARD	Torn	175.00 FL	*175.00 FL
22	2		*REAR FLOOR PANEL TOP SPONGE (SIDE)	Torn	550.00 FL	*550.00 FL
23	1		*REAR FLOOR PANEL TOP SPONGE (INNER)	Not Necessary	240.00 FL	*- FL
24	1		*REAR NUMBER PLATE AND FRAME	Cracked	50.00 FS	*40.00 FS
25	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
26	1		*BOOT LID SEALANT	Not Necessary	150.00 FS	*- FS
27	1		*SET BOOT LID OUTER MOULDING CLIP	Not Necessary	40.00 FS	*- FS
28	1		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
29	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
30	1		*SET TAIL LAMP CLIPS	Not Necessary	30.00 FS	*- FS
31	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*50.00 FS
32	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	40.00 FS	*- FS
33	1		*SET REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					7,184.00	4,630.40
- List Item Discount on L Items 25.00/25.00% (\$\$)					1,576.00	1,072.60
Total Parts (\$\$)					5,608.00	3,557.80
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD, CUT ,KNOCK GRAZE ADJUST REPLACE NEW PARTS	New	1,400.00	1,200.00
2	TO PUTTY ,SRPAY PAINT ,POLISH WAX ADJACENT PANELS	New	1,400.00	1,200.00
3	TUFF COAT	New	250.00	80.00
4	WIRING /BULB CHECKING	New	180.00	20.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	350.00	100.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	TRANSFER BOOT LID MECHANISM	New	80.00	60.00
8	TO CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
9	REAR CHASSIS MEMBER ALIGNMENT	New	250.00	0.00
Gross Labour Cost (\$\$)			4,070.00	2,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >