

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22008599/KYA3Q2**Date:** 17/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210073236
<b>Claimant Vehicle No :</b>	SHB9573Z	<b>Insured Vehicle No :</b>	SLF5291U
Date of Loss:	16/08/2022	Nature of Claim:	TP
		Claim No:	5419665641SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB9573Z</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B79069
Reg. Date:	04/12/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU503077203
Colour:	Metallic Pearl White/Red	Odometer:	460158 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	HARMONIC 9 mm	Rear Left Side:	Wanli 9 mm
Front Right Side:	HARMONIC 9 mm	Rear Right Side:	Wanli 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,223.45	1,074.17	4,149.28	79.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	435.00	3,155.00	87.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,813.45</b>	<b>1,509.17</b>	<b>7,304.28</b>	<b>82.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>(S\$)</b>	8,813.45	1,200.00	7,613.45	86.38
<b>+ GST 7.00/7.00% (S\$)</b>	616.94	84.00	532.94	86.38
<b>Nett Amount (S\$)</b>	<b>9,430.39</b>	<b>1,284.00</b>	<b>8,146.39</b>	<b>86.38</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$96.30/day) (S\$)</b>		288.90		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>1,730.35</b>		

INSPECTION

Date of Assignment:	18/08/2022		
Date Inspected:	18/08/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

**Adjuster:** KENNETH KONG**Manager:** Ezlyna

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled / Dented	442.60 FL	*442.60 FL
2	1		*GUARD ,REAR BUMPER CENTER	Dented / Cut	576.30 FL	*576.30 FL
3	1		*COVER ,REAR BUMPER ,LOWER	Serviceable	15.40 FL	*- FL
4	1		*FILLER REAR BUMPER EXTENSION ,LH	Serviceable	123.70 FL	*- FL
5	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	116.50 FL	*- FL
7	1		*LENS & BODY ,REAR COMBINATION LAMP ,LH (UPPER )	Serviceable	443.30 FL	*- FL
8	1		*LENS AND BODY ,REAR LAMP ,LH (LOWER)	Serviceable	502.00 FL	*- FL
9	1		*COVER ,REAR COMBINATION LAMP ,LH	Serviceable	64.50 FL	*- FL
10	1		*COVER ,FLOOR UNDER NO.1 LH	Serviceable	175.10 FL	*- FL
11	1		*COVER ,REAR FLOOR CTR	Serviceable	229.90 FL	*- FL
12	1		*COVER ,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
13	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	650.30 FL	*- FL
14	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Serviceable	925.60 FL	*- FL
15	1		*PARKING AID	Dented	700.00 FS	*220.00 FS
16	1		*TYRE	Serviceable	300.00 FS	*- FS
17	1		*REAR FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
18	1		*REAR LOWER BUMPER CLIP	Not Necessary	65.00 FS	*- FS
19	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
20	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
21	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
22	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	*30.00 FS
23	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
24	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,404.60	1,328.90
- List Item Discount on L Items 25.00/25.00% (\$)	1,181.15	254.73
Total Parts (\$)	5,223.45	1,074.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,400.00	200.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	220.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,590.00</b>	<b>435.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >