



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 1807U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT LH DOOR	TO REPAIR SEE LABOUR	1,808.30	-
1	FRONT LH DOOR INNER LOCK	SERVICEABLE	607.90	-
1	FRONT LH DOOR WEATHERSTRIP	NOT NECESSARY	188.60	-
1	REAR LH SLIDING DOOR	BUCKLED	1,966.10	1,594.00
1	REAR LH SLIDING DOOR INNER BOARD	BROKEN	685.30	620.00
1	REAR LH SLIDING DOOR INNER LOCK	FAULTY	983.50	500.00
1	REAR LH SLIDING DOOR WEATHERSTRIP	NOT NECESSARY	234.80	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	1,261.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	873.90	-
1	REAR BUMPER SIDE LH	NOT NECESSARY	300.60	-
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	96.80	-
1	REAR BUMPER SIDE BRACKET LH	NOT NECESSARY	160.66	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	125.30	-
1	REAR LH WHEEL HUB WITH BEARING	FAULTY	966.80	450.00
1	REAR LH KNUCKLE ARM	NOT NECESSARY	688.80	-
1	REAR LH SHOCK ABSORBER	NOT NECESSARY	441.30	-
1	REAR LH LOWER ARM	NOT NECESSARY	996.40	-
	LESS 25% DISCOUNT		-3,096.52	-791.00
			9,289.54	2,373.00
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	80.00	-
1	REAR LH TYRE (SN)	NOT NECESSARY	400.00	-
1	REAR LH WHEEL RIM (SN)	TO REPAIR SEE LABOUR	1,219.30	-
			1,699.30	-
<u>LABOUR</u>				
	TO PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT LH DOOR, REAR LH FENDER, REAR BUMPER AND REAR LH WHEEL RIM.		2,200.00	800.00

Report Ref No. CS/SMR22008600/Sqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND RESPRAY ON ACCIDENT PORTION.		2,200.00	800.00
	TO CHECK WIRING.		80.00	30.00
	REMOVE & REFIX FRONT WINDSCREEN.	NOT NECESSARY	120.00	-
	TRANSFER FRONT DOOR MECHANISM.	NOT NECESSARY	80.00	-
	REMOVE & REFIX REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TRANSFER REAR SLIDING DOOR MECHANISM.		80.00	60.00
	TO CHECK WIRING.	REPEATED	80.00	-
			4,960.00	1,690.00
	GRAND TOTAL		15,948.84	4,063.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,250.00

Report Ref No. CS/SMR22008600/Sqy3e2

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.