

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22008601/ACM4**Date:** 05/12/2022**REFERENCE**

Insured/Claimant:	TANG MEI LING	Policy No:	2070168524	
Date of Loss:	30/08/2022	Nature of Claim:	OD	Claim No: 1139627790SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW7842R		
Make & Model:	AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A)	Engine No:	CHZC35607
Reg. Date:	10/12/2020 (Man. Year: 2019)	Chassis No:	WAUZZZ8V4LA006395
Colour:	Red	Odometer:	47957 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$128,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,340.00	3,804.48	1,535.52	28.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,222.00	2,602.00	1,620.00	38.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,562.00	6,406.48	3,155.52	33.00
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	8,962.00	5,806.48	3,155.52	35.21
+ GST 7.00/7.00% (S\$)	627.34	406.45	220.89	35.21
Nett Amount (S\$)	9,589.34	6,212.93	3,376.41	35.21

INSPECTION

Date of Assignment:	02/09/2022	
Date Inspected:	02/09/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Dented	3,265.00 FS	*2,612.00 FS
2	1		*REAR OUTER DOOR SEAL - LH	Necessary	179.00 FS	*142.80 FS
3	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
6	1		*REAR DOOR CATCH - LH	Not Necessary	105.00 FS	*- FS
7	1		*REAR ALUMINIUM RIM - LH	Cut	1,303.00 FS	*1,042.40 FS
8	1		*REAR ALUMINIUM RIM RUBBER VALVE - LH	Necessary	4.00 FS	*2.96 FS
9	1		*SUNDRIES	Necessary	350.00 FS	*4.32 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					5,340.00	3,804.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	280.00
2	TO DISMANTLE AND RENEW LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,400.00	750.00
3	TO RESPRAY LHS REAR DOOR AND LHS REAR FENDER	New	2,000.00	1,100.00
4	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			4,222.00	2,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >