

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR22008602/Eqy3e2	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 17705		Date:	15/09/2022	
				Code:	SMR	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHF 489Y	Veh. Inspected	l	FBN 17E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/08/22/2047	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		02/09/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	KYMCO K-XCT200I	c.c		199	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	RFBD82000E1000119	Colour		BLUE	
	Odometer	7809 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	120/70-14	MICHELIN		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70-14	MICHELIN		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S				
5.	General Information					
	Accident Date	18/08/2022	Inspect Date /	Time	02/09/2022 ( 05:56 PM )	
	Survey held at HUA CHIN (2000) TRADING MOTOR SVC CENTRE					
	50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b. Estimate Days of Repair						
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/SMR22008602/Eqy3e2

Inspected By

CHEN TSUE YEE

EE K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser