

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 789Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	COVER, RR BUMPER (SN)	DEFORMED	1,248.40	1,248.40
1	EXTENSION SUB-ASSY (SN)	SCRATCHED	881.20	881.20
6	PIECE, RR BUMPER (SN)	NECESSARY	27.00	27.00
16	RETAINER, OUTSIDE (SN)	NECESSARY	68.80	68.80
1	SUPPORT, RR BUMPER (SN)	NOT NECESSARY	278.20	-
1	SUPPORT, RR BUMPER (SN)	NOT NECESSARY	278.20	-
2	TAPE, MOULDING, NO.1 (SN)	NECESSARY	111.00	111.00
1	SUPPORT, RR BUMPER (SN)	NOT NECESSARY	124.00	-
1	SUPPORT, RR BUMPER (SN)	NOT NECESSARY	124.00	-
1	ABSORBER, RR BUMPER (SN)	CRACKED	138.10	138.10
1	REINFORCEMENT (SN)	NOT NECESSARY	966.10	-
4	SENSOR, ULTRASONIC (SN)	NOT NECESSARY	1,965.60	-
1	REFLECTOR ASSY (SN)	NOT NECESSARY	52.70	-
1	REFLECTOR ASSY (SN)	NOT NECESSARY	52.70	-
			6,416.00	2,524.50
	<u>LABOUR</u>			
	TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON REAR BUMPER, REAR PANEL AND FIX NEW PARTS.		1,732.00	866.00
	TO SPRAY PAINT ON REAR BUMPER.		1,484.00	742.00
	TO REMOVE AND TRANSFER REAR SENSOR TO NEW BUMPER, REPLACE IF DAMAGE.		216.50	216.50
	TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST.		216.50	216.50
	TO RESET ECU AND REPROGRAMME.		216.50	216.50
			3,865.50	2,257.50
	GRAND TOTAL		10,281.50	4,782.00



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 4,782.00

Report Ref No. CS/SMR22008604/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator