



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 2839M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER ASSY	CUT / TORN	1,693.00	803.00
1	FRONT LEFT BUMPER FOG LAMP GARNISH	NOT NECESSARY	68.00	-
1	FRONT LEFT BUMPER FOG LAMP	NOT NECESSARY	275.00	-
1	FRONT BUMPER LOWER SPOILER	GRAZED	1,250.00	680.00
1	FRONT BUMPER LEFT SIDE RETAINER	BENT	46.00	35.00
1	FRONT BUMPER CENTER LOWER GRILLE	NOT NECESSARY	162.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	323.00	-
1	FRONT BUMPER TOW COVER	NOT NECESSARY	65.00	-
1	FRONT BUMPER LEFT BRACKET	NOT NECESSARY	48.00	-
1	FRONT BUMPER LEFT DAYLAMP	NOT NECESSARY	850.00	-
1	FRONT LEFT HEADLAMP ASSY	NOT NECESSARY	1,461.00	-
1	FRONT LEFT FENDER	DENTED	1,291.00	622.00
1	FRONT LEFT FENDER INNER SHIELD	NOT NECESSARY	129.00	-
1	FRONT LEFT FENDER PROTECTOR	GRAZED	192.00	192.00
1	FRONT LEFT SUSPENSION ASSY	NOT NECESSARY	966.00	-
1	FRONT LEFT LOWER ARM	NOT NECESSARY	622.00	-
1	FRONT LEFT LOWER ARM BALL JOINT	NOT NECESSARY	156.00	-
1	FRONT LEFT KNUCKLE ARM	NOT NECESSARY	433.00	-
1	FRONT LEFT WHEEL BEARING	NOT NECESSARY	255.00	-
1	FRONT LEFT DRIVE SHAFT	NOT NECESSARY	1,456.00	-
1	FRONT STABILIZER BAR	NOT NECESSARY	298.00	-
1	FRONT LEFT STABILIZER BAR LINKAGE	NOT NECESSARY	185.00	-
1	FRONT GRILLE ASSY	NOT NECESSARY	285.00	-
1	FRONT GRILLE CHROME MOULDING	NOT NECESSARY	166.00	-
1	FRONT GRILLE EMBLEM	NOT NECESSARY	87.00	-
	LESS 10% DISCOUNT		-1,276.20	-233.20
			11,485.80	2,098.80
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT LEFT WHEEL RIM (SN)	CUT	750.00	600.00
1	FRONT LEFT TYRE (SN)	NOT NECESSARY	300.00	-

Report Ref No. CS/SMR22008606/Uvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET FRONT BUMPER LOWER SPOILER CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CENTER LOWER GRILLE CLIPS (SN)	NOT NECESSARY	40.00	-
1	SET FRONT LEFT FENDER PROTECTOR CLIPS (SN)	NECESSARY	30.00	30.00
1	SET FRONT LEFT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	30.00	-
6	FRONT GRILLE CLIPS (SN)	NOT NECESSARY	40.00	-
6	FRONT GRILLE CHROME MOULDING CLIPS (SN)	NOT NECESSARY	40.00	-
			1,330.00	660.00
	LABOUR			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT LEFT AFFECTED AREA AND REPLACE FRONT LEFT DAMAGED PARTS.		1,200.00	320.00
	TO PUTTY AND SPRAY PAINTING FRONT AND FRONT LEFT PORTION.		1,200.00	580.00
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.		50.00	20.00
	TO REMOVE AND INSTALL FRONT BONNET LOCK, MECHANISM.	NOT NECESSARY	80.00	-
	TO APPLY ANTI RUST PROOFING TO FRONT LEFT AFFECTED AREA.		140.00	30.00
	TO REMOVE AND INSTALL FRONT LEFT UNDERCARRIAGE PARTS.	NOT NECESSARY	350.00	-
	TO BALANCE FRONT LEFT WHEEL.	NOT NECESSARY	50.00	-
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TOWING SERVICE.	NOT NECESSARY	100.00	-
			3,320.00	1,010.00
GRAND TOTAL			16,135.80	3,768.80

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00
---	--	--	-----------------

Report Ref No. CS/SMR22008606/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.