

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008611/ANY3Q2**Date:** 28/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00148462100		
Claimant Vehicle No :	SJG315L	Insured Vehicle No :	GBF364U		
Date of Loss:	30/08/2022	Nature of Claim:	TP	Claim No:	SNM22D206197/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG315L	Engine No:	3SZ2033871
Make & Model:	TOYOTA RUSH, 1.5 X (A)	Chassis No:	J200E0019658
Reg. Date:	18/06/2008 (Man. Year: 2007)	Odometer:	166077 km
Colour:	Silver		
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,895.22	4,482.90	2,412.32	34.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,830.00	480.00	20.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,205.22	6,312.90	2,892.32	31.42
Approved Total (Overridden) (\$\$)		5,000.00		
	9,205.22	5,000.00	4,205.22	45.68
+ GST 7.00/7.00% (\$\$)	644.37	350.00	294.37	45.68
Nett Amount (\$\$)	9,849.59	5,350.00	4,499.59	45.68

INSPECTION

Date of Assignment:	02/09/2022	
Date Inspected:	02/09/2022 Inspected At:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Sep 2022)
Parts: M1-SUV	TOYOTA RUSH 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG315L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	695.50 FL	*695.50 FL
2	2		*REAR BUMPER NUMBER PLATE LAMP L/R	Cracked	1,055.60 FL	*136.00 FL
3	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	105.60 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	179.20 FL	*- FL
5	1		*REAR END PANEL	Dented	317.80 FL	*317.80 FL
6	1		*REAR END PANEL INNER TOP GARNISH	Deformed	274.30 FL	*274.30 FL
7	1		*REAR TAILGATE	Dented	2,107.10 FL	*1,404.00 FL
8	1		*REAR TAILGATE RUSH EMBLEM	Necessary	79.20 FL	*79.20 FL
9	1		*REAR TAILGATE HINGE (LOWER)	Not Necessary	168.10 FL	*- FL
10	1		*REAR TAILGATE HINGE (TOP)	Not Necessary	168.10 FL	*- FL
11	2		*REAR TAILGATE INNER RUBBER GUIDE STOPPER	Not Necessary	60.80 FL	*- FL
12	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	319.60 FL	*319.60 FL
13	1		*REAR TAILGATE MECHANISM LOCK	Not Necessary	188.20 FL	*- FL
14	1		*REAR TAILGATE SPARE TYRE BRACKET	Not Necessary	290.40 FL	*- FL
15	1		*REAR TAILGATE SPARE TYRE COVER (INNER)	Cracked	335.30 FL	*335.30 FL
16	1		*REAR TAILGATE SPARE TYRE COVER (OUTER)	Deformed	1,704.80 FL	*1,704.80 FL
17	1		*REAR TAILGATE WEATHER STRIP	Cut	270.70 FL	*270.70 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
19	1		*REAR BUMPER NUMBER PLATE	Not Necessary	25.00 FS	*- FS
20	1		*REAR BUMPER NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
21	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
22	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*10.00 FS
23	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
24	1		*REAR TAILGATE WINDSCREEN SEAL	Necessary	80.00 FS	*30.00 FS
25	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,975.30	5,867.20
- List Item Discount on L Items 25.00/25.00% (\$)	2,080.08	1,384.30
Total Parts (\$)	6,895.22	4,482.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	60.00
2	TO REMOVE REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	100.00	30.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
5	TO PROVIDE LABOUR WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENT	New	800.00	700.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	40.00
7	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
Gross Labour Cost (\$\$)			2,310.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >