

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22008613/ANY3E2**Date:** 22/12/2022REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMB1SNW00012572101

**Claimant Vehicle  
No :** GBK7586Z**Insured Vehicle  
No :** PC8300B

Date of Loss: 28/07/2022

Nature of Claim: TP

Claim  
No: SNM22D205728/C02/TAYHPDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBK7586Z**

Make &amp; Model: TOYOTA DYNA 150, 3.0 D 5MT (M)

Engine No: 1KDB050145

Reg. Date: 23/11/2020 (Man. Year: 2020)

Chassis No: JTFAT35Y20K215760

Colour: Silver

Odometer: 88829 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Rear Tyre Size: 155 R12C

Front Left Side: Bridgestone 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,012.64	2,332.18	4,680.46	66.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	930.00	1,250.00	57.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,192.64</b>	<b>3,262.18</b>	<b>5,930.46</b>	<b>64.51</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,192.64</b>	<b>2,600.00</b>	<b>6,592.64</b>	<b>71.72</b>

INSPECTION

Date of Assignment: 20/12/2022

Date Inspected: 02/09/2022

Inspected At: Cheng Motor Work Co. (HQ)  
1 KAKI BUKIT AVE 6 #01-83  
Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 22 Dec 2022)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBK7586Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR L/H	Dented	1,657.92 F	*1,485.00 FL
2	1		*FRONT DOOR RUBBER	Not Necessary	225.72 F	*- FL
3	1		*ARCH PANEL RUBBER	Not Necessary	112.20 F	*- FL
4	2		*FRONT DOOR HINGE	Not Necessary	309.32 F	*- FL
5	1		*DOOR WINDOW OUTER MOULDING	Not Necessary	165.66 F	*- FL
6	1		*DOOR WINDOW CHANNELS	Not Necessary	268.07 F	*- FL
7	1		*DOOR CHECKERS	Not Necessary	198.99 F	*- FL
8	1		*DOOR OUTER HANDLE	Not Necessary	224.73 F	*- FL
9	1		*FRONT CORNER PANEL	Repair	369.93 F	*- FL
10	1		*FRONT HEADLAMP	Cut	1,296.57 F	*1,296.57 FL
11	1		*FRONT SIDE MIRROR L/H	Cut	308.00 F	*308.00 FL
12	1		*FRONT ROUND MIRROR	Not Necessary	108.46 F	*- FL
13	1		*FRONT SIDE MIRROR MOTOR	Not Necessary	685.90 F	*- FL
14	1		*FRONT BUMPER	Repair	823.35 F	*- FL
15	1		*STEP GARNISH	Not Necessary	237.82 F	*- FL
16	1		*SIDE MARKER	Necessary	20.00 F	*20.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>7,012.64</b>	<b>3,109.57</b>
<b>- List Item Discount on L Items 0.00/25.00% (S\$)</b>	0.00	777.39
<b>Total Parts (S\$)</b>	<b>7,012.64</b>	<b>2,332.18</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR KNOCKING FLOOR PANEL, WELDING, CUTTING, REPAIRING AND REPLACEMENT OF PARTS	New	800.00	300.00
2	TO SPRAY PAINT ON THE DAMAGE PARTS	New	1,000.00	500.00
3	TO DISMANTLE AND TRANSFER DOOR MECHANICAL	New	150.00	60.00
4	TO CHECK WIRING	New	80.00	30.00
5	TO APPLY RUST-PROOFING	New	150.00	40.00
<b>Gross Labour Cost (S\$)</b>			<b>2,180.00</b>	<b>930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >