

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83
SINGAPORE 417883
Tel:65551185/6 Fax:65551184
H/P: 96713335
E-mail:chengmotor27@yahoo.com

JTFA735Y20K215760

30/8/2022

China Taiping Insurance (S) Pte. Ltd.
3 Anson Road #16-00
Springleaf Tower.
Singapore 079909
Attn: motor claims Dept

Xiao Chen.

Estimate cost of repair vehicle no: GBK7586Z

Front Door L/h *Dented*
Front door rubber *3 new*
Arch Panel Rubber *3 new*
2pc front door hinge \$154.66x2 *new*
Door window outer Moulding *3 new*
Door window channels
Door checkers *new*
Door outer handle *new*
Front conner Panel *Rep*
Front Headlamp *let*
Front side mirror L/h *let*
Front round mirror *new*
Front side mirror motor *new*
Front bumper *Rep*
Step garnish *new*
Side marker *new*

1657.92	<i>1485</i>
225.72	<i>+</i>
112.20	<i>+</i>
309.32	<i>+</i>
165.66	<i>+</i>
268.07	<i>+</i>
198.99	<i>+</i>
224.73	<i>+</i>
369.93	<i>+</i>
1296.57	<i>3109.87</i>
308.00	<i>2332.177</i>
108.46	<i>+</i>
685.90	<i>+</i>
823.35	<i>+</i>
237.82	<i>+</i>
20.00	<i>+</i>

Labour for knocking floor Panel,welding,cutting,repairing
And replacement of parts.
To spray paint on the damage parts.
To dismantle and transfer door mechanical
To check wiring
To apply rust- proofing

800.00	<i>300</i>
1000.00	<i>500</i>
150.00	<i>60</i>
80.00	<i>30</i>
150.00	<i>40</i>

930

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 3062.17 *Attn: Lin*
L/S: 2.6K. *4/5 02/29/22*

04 Days.