

REPAIR ESTIMATE*

VEHICLE NO SHA1225L

27.08.2022

MAKE REG: 29.12.2016

MODEL HYU- I40

Type

CHIANG/ NTUC

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER COVER X Rep ✓ CRA		\$553.00 ✓
1	REAR BUMPER LOWER COVER X		\$228.00
1	REAR BUMPER REINFORCEMENT X		\$428.40
10	REAR BUMPER CLIPS X } nn	\$2.20	\$22.00
2	REAR BUMPER BRACKET LH/RH X	\$35.60	\$71.20
2	REAR BUMPER REFLECTOR LH/RH X	\$32.00	\$64.00
	SUB TOTAL		\$1,366.60
	20.00%		\$273.32
	DISCOUNTED TOTAL		\$1,093.28
1	REAR BUMPER MAT X } nn		\$50.00
1	REAR REVERSE SENSOR X } nn		\$135.70
			\$172.13
	Labour Charge		
	Panel Beating		\$450.00 280
	Spray Painting Charge		\$300.00 250
	Remove/refix reverse sensor		\$60.00 40
	Check Lighting & Wiring		\$40.00 X
	TOTAL LABOUR		\$850.00
	ESTIMATE TOTAL		\$2,115.41
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

27 Aug.

L/S

Gur Af

30/8/22

11AM

-20%: 800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date: