



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7364D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER ASSY	TORN	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	CRACKED	451.25	451.25
1	REAR BUMPER BEAM	NOT NECESSARY	394.80	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR FOG LAMP	NOT NECESSARY	201.50	-
1	ANTENNA - SMARTKEY	NOT NECESSARY	40.50	-
	LESS 20% DISCOUNT		-313.89	-186.53
			1,255.56	746.12
	<b><u>NETT ITEMS</u></b>			
1	REAR NUMBER PLATE (N)	CRACKED	50.00	50.00
	LESS 10% DISCOUNT		-	-5.00
			50.00	45.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	BUMPER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINT.		300.00	250.00
	REMOVE / REFIX REVERSE SENSOR.		50.00	40.00
			750.00	640.00
	<b>GRAND TOTAL</b>		<b>2,105.56</b>	<b>1,481.12</b>
	<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>1,481.12</b>

Report Ref No. NS/INC22008626/Gcm4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.