

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008630/AYA3Q2**Date:** 17/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070174862
Claimant Vehicle No :	SMC7180Y	Insured Vehicle No :	SMX5291M
Date of Loss:	30/08/2022	Nature of Claim:	TP
		Claim No:	8183067897SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC7180Y		
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A)	Engine No:	G4FGJU205235
Reg. Date:	19/07/2018 (Man. Year: 2018)	Chassis No:	KMHD841CMJU703748
Colour:	Red	Odometer:	101432 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,770.40	5,105.28	4,665.12	47.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,730.00	3,040.00	1,690.00	35.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,500.40	8,145.28	6,355.12	43.83
Approved Total (Overridden) (\$\$)		6,500.00		
Nett Amount (\$\$)	14,500.40	6,500.00	8,000.40	55.17
+ Loss of Use (9.0 x S\$60.00/day) (\$\$)		540.00		
Nett Liability (\$\$)		7,040.00		

INSPECTION

Date of Assignment:	01/09/2022	
Date Inspected:	01/09/2022 Inspected At:	ADVANCE AUTO GARAGE (23 KAKI BUKIT) (HQ) 25 KAKI BUKIT AVE 4 #04-01 VICOM KAKI BUKIT Singapore 415933
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	495.50 F	*495.50 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*REAR BUMPER SIDE HOLDER LH	Damaged	38.20 F	*38.20 FL
4	1		*REAR BUMPER LOWER GARNISH	Deformed	305.40 F	*305.40 FL
5	1		*REAR BUMPER REFLECTOR LH	Missing	72.50 F	*72.50 FL
6	1		*REAR BUMPER REINFORCEMENT	Dented	329.80 F	*329.80 FL
7	1		*REAR BUMPER UNDERCOVER LH	Torn	98.60 F	*98.60 FL
8	1		*REAR BUMPER UNDERCOVER CLIPS	Necessary	20.00 FS	*20.00 FS
9	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
10	1		*REAR END PANEL	Dented	569.40 F	*569.40 FL
11	1		*REAR END PANEL TOP GARNISH	Deformed	142.30 F	*142.30 FL
12	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
13	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
14	1		*TAILLAMP LH	Cracked	598.00 F	*598.00 FL
15	1		*TAILLAMP PANEL LH	Dented	188.90 F	*188.90 FL
16	1		*REAR FENDER LH	Distorted	1,768.30 F	*1,768.30 FL
17	1		*REAR FENDER INNER TRIM BOARD LH	Torn	345.20 F	*345.20 FL
18	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
19	1		*REAR FENDER INNER SHIELD LH	Not Necessary	146.80 F	*- FL
20	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	20.00 FS	*- FS
21	1		*REAR FENDER INNER PANEL LH	Repair	899.80 F	*- FL
22	1		*REAR FENDER AIR VENT	Cracked	38.90 F	*38.90 FL
23	1		*REAR WINDSCREEN MOULDING	Necessary	168.40 F	*168.40 FL
24	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
25	1		*BOOTLID	Repair	1,782.10 F	*- FL
26	1		*BOOTLID LOCK	Not Necessary	166.70 F	*- FL
27	1		*BOOTLID WEATHERSTRIPE	Cut	152.60 F	*152.60 FL
28	1		*BOOTLID REFLECTOR LH	Cut	402.90 F	*402.90 FL
29	1		*ELANTRA WORDING	Necessary	49.90 F	*49.90 FL
30	1		*S EMBLEM	Necessary	48.90 F	*48.90 FL
31	1		*HYUNDAI LOGO	Necessary	42.90 F	*42.90 FL
32	1		*SPARE TYRE SIDE PANEL LH	Repair	338.40 F	*- FL
33	1		*SPARE TYRE SIDE PANEL SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,770.40	6,276.60
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,171.32
Total Parts (S\$)	9,770.40	5,105.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	1,400.00
2	SPRAY PAINTING	New	1,800.00	1,300.00
3	WIRING	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO SPRAY TUFF COAT	New	150.00	80.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	0.00
8	TO REMOVE REAR WINDSCREEN	New	180.00	120.00
9	TO REMOVE REAR CAMERA	New	100.00	0.00
Gross Labour Cost (\$\$)			4,730.00	3,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >