

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008633/AYA3Q2**Date:** 14/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800100545
Claimant Vehicle No :	SDS8899Z	Insured Vehicle No :	SDD1052A
Date of Loss:	01/09/2022	Nature of Claim:	TP
		Claim No:	7224506178SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDS8899Z	Engine No:	2AZF210924
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Chassis No:	ACR500081653
Reg. Date:	16/03/2009 (Man. Year: 2008)	Odometer:	257550 km
Colour:	White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,313.60	4,286.67	5,026.93	53.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	2,220.00	1,210.00	35.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,743.60	6,506.67	6,236.93	48.94
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	12,743.60	5,200.00	7,543.60	59.20
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,807.45		

INSPECTION

Date of Assignment:	01/09/2022		YSK Auto Workshop (HQ)
Date Inspected:	01/09/2022	Inspected At:	1 Kaki Bukit Avenue 6 @ AutoBay, #01-71
Estimated Period of Repair:	6.0 days		Singapore 417883

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER	Deformed	765.40 F	*765.40 FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	2		*REAR BUMPER SIDE HOLDER	Necessary	124.80 F	*124.80 FL
6	2		*REAR BUMPER REFLECTOR	Not Necessary	133.80 F	*- FL
7	2		*REAR BUMPER TOW COVER	Not Necessary	94.00 F	*- FL
8	4		*REVERSE SENSOR	Damaged	350.00 FS	*280.00 FS
9	1		*REAR END PANEL	Dented	645.10 F	*645.10 FL
10	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
11	1		*REAR END PANEL TOP GARNISH	Deformed	308.20 F	*308.20 FL
12	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
13	1		*REAR END PANEL LOWER GARNISH	Deformed	194.20 F	*194.20 FL
14	1		*REAR END PANEL LOWER GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
15	1		*TAILGATE	Dented	1,635.40 F	*1,635.40 FL
16	1		*TAILGATE LOCK	Damaged	371.50 F	*371.50 FL
17	1		*TAILGATE WEATHERSTRIPE	Not Necessary	311.70 F	*- FL
18	1		*TAILGATE INNER TRIM BOARD	Not Necessary	495.90 F	*- FL
19	1		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
20	1		*TAILGATE GLASS MOULDING	Necessary	182.50 F	*182.50 FL
21	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
22	1		*TOYOTA LOGO	Necessary	56.70 F	*56.70 FL
23	1		*ESTIMA WORDING	Necessary	59.40 F	*59.40 FL
24	1		*AERUS WORDING	Necessary	58.50 F	*58.50 FL
25	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	1,390.80 F	*- FL
26	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
27	1		*FLOOR PANEL	Repair	1,048.50 F	*- FL
28	1		*FLOOR PANEL SEALANT	Not Necessary	60.00 FS	*- FS
29	1		*FLOOR PANEL TOP FOLDABLE BOARD	Deformed	687.20 F	*687.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,313.60	5,558.90
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,272.23
Total Parts (\$)	9,313.60	4,286.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	900.00
2	SPRAY PAINTING	New	1,200.00	900.00
3	WIRING	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	100.00	50.00
6	TO SPRAY TUFF COAT	New	100.00	60.00
7	TO REMOVE REAR CAMERA	New	100.00	50.00
8	TO REMOVE TAILGATE GLASS	New	180.00	120.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
			Gross Labour Cost (S\$)	3,430.00
				2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >