



## Case Details

Case Reference Number : TAX/09/22/2003  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB1158S

Company Type : Strides Taxi Pte Ltd  
 Estimation ID : EST-19260-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : income insurance limited  
 Accident Date and Time : 01/09/2022, 10:15 AM  
 Vehicle Age(In Months) : -

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dist(%)	Final Price(\$)	Repair/ Replace	Surveyor Approval			Remarks
											Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			HOOD ASM	1	2,407.29	2,407.29	10.00	2,166.56	Replace	0	0	Not Given	XAN
Standard	Main			MODULE-FRT END	1	295.26	295.26	10.00	265.73	Replace	0	0	Not Given	XAN
Standard	Main			FASCIA-FRT BPR	1	721.66	721.66	10.00	649.49	Replace	1	649.49	Replace	de-
Standard	Main			GRILLE-FRT BPR FASCIA LOWER	1	149.03	149.03	10.00	134.13	Replace	0	0	Not Given	XAN
Standard	Main			FINISHER-FRT BPR-LH	1	98.80	98.80	10.00	88.92	Replace	0	0	Not Given	XAN
Standard	Main			FINISHER-FRT BPR-RH	1	98.80	98.80	10.00	88.92	Replace	0	0	Not Given	XAN
Standard	Main			SUPPORT-FRT BPR FASCIA UPR	1	172.33	172.33	10.00	155.10	Replace	0	0	Not Given	XAN
Standard	Main			PANEL ASM-LEG CTHR	1	131.04	131.04	10.00	117.94	Replace	0	0	Not Given	XAN
Standard	Main			BAR ASM-FRT BPR IMP	1	624.00	624.00	10.00	561.60	Replace	0	0	Not Given	XAN
Standard	Main			GRILLE ASM-RAD	1	978.02	978.02	10.00	880.22	Replace	1	880.22	Replace	ca-
Standard	Main			COVER-FICMPT ORNA	1	217.67	217.67	10.00	195.90	Replace	0	0	Not Given	XAN
Standard	Main			BRACKET-FICMPT TR PLT	1	55.33	55.33	10.00	49.80	Replace	0	0	Not Given	XAN

Total Spare Part Cost 7,432.31

Lump Sum Discount (%) 0.00

Final Spare Part Cost 7,432.31

Surveyor Total 1,589.71

Lump Sum Dis (%) 0

Final Sur Total 1,589.71

BOM Type	Costing Type	Portion	SMRT Recommendation				Surveyor Approval						
			Material Number	Part Name	Qty	List Price Per Unit(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Final Price(\$)	Repair/Replace	Remarks	
Standard	Main			BRACKET-FICMPT TR PLT	1	44.51	10.00	40.06	Replace	0	0	Not Givt	XAN
Standard	Main			HEADLAMP ASM-LH	1	1,098.86	10.00	988.97	Replace	0	0	Not Givt	XAN
Standard	Main			HEADLAMP ASM - RH	1	1,098.86	10.00	988.97	Replace	0	0	Check	7, XAN
Standard	Main			NUMBER PLATE	1	35.00	0.00	35.00	Replace	1	35.00	Replace	bf
Standard	Main			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	1	25.00	Replace	cut
Total Spare Part Cost									7,432.31	Surveyor Total		1,589.71	
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0	
Final Spare Part Cost									7,432.31	Final Sur Total		1,589.71	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,200.00	250.00	
Total:			1,200.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	428.00	220.00	
2	Main	TO RESPRAY FRONT HOOD	428.00	0.00	XAN
Total:			856.00	220.00	

Other Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	112.00	0	XAN request invoice
2	Main	TO WASH AND VACUUM	60.00	0	XAN
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0	XAN
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	XAN
Total:			992.00	300.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150.00	
6	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
7	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 <i>Xm</i>	
<b>Total:</b>			<b>992.00</b>	<b>300.00</b>	<b>✓</b>

### Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	7,432.31	1,589.71
Total Labour Cost	1,200.00	250.00
Total Spray Painting	856.00	220.00
Other	992.00	300.00
<b>Overall Total</b>	<b>10,480.31</b>	<b>2,359.71</b>
Lump Sum Repair Option	<input type="checkbox"/>	<input type="checkbox"/>
Lump Sum Total	0.00	2,359.71
Surveyor Approved Amount		2,359.71
No of Repair Days*	5	3

Remarks: Part by part / Before paint photo , After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068, email.

Surveyor Name: Rosul  
 Signature:   
 Signature:   
 Survey Date: 02/09/2022  
 Buttons: Save, Clear

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: