

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 5788B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED / WARPED	985.20	762.40
1	FRONT BUMPER LOWER	NOT NECESSARY	650.00	-
1	FRONT BUMPER SIDE RETAINER N/S	NOT NECESSARY	66.50	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	45.00
1	FRONT BUMPER BEAM	NOT NECESSARY	381.00	-
1	HEADLAMP N/S	HOLDER CRACKED	1,959.20	1,959.20
1	FRONT FENDER N/S	TO REPAIR SEE LABOUR	788.10	-
1	FRONT FENDER OUTER PROTECTOR N/S	GRAZED	388.50	280.40
1	FRONT FENDER INNER SHIELD N/S	NOT NECESSARY	315.10	-
1	SET FRONT FENDER INNER SHIELD CLIPS N/S	NOT NECESSARY	50.00	-
1	FRONT GRILLE	NOT NECESSARY	288.20	-
	LESS 20% DISCOUNT		-	-609.40
			5,921.80	2,437.60
	<u>LABOUR</u>			
	TO CHECK WIRING.		30.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	40.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO RESET & REPROGRAMME SYSTEM.	NOT NECESSARY	120.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER N/S.		600.00	280.00
	TO PUTTY & SPRAY PAINTING.		900.00	400.00
			1,810.00	700.00
	GRAND TOTAL		7,731.80	3,137.60

RECOMMENDED COST OF LUMP SUM REPAIRS		2,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI22008649/Uvy3e2





Report Ref No. CS/AGI22008649/Uvy3e2

CHUA KANG SENG Licensed Appraiser