

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22008657/RPA3Q2**Date:** 01/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220018771
<b>Claimant Vehicle No :</b>	SHB883M	<b>Insured Vehicle No :</b>	SNE1658D
Date of Loss:	02/09/2022	Nature of Claim:	TP
		Claim No:	1642295223SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB883M</b>		
Make & Model:	M.G. MG5, EV EXCITE T (M)	Engine No:	HIDDEN
Reg. Date:	29/12/2021 (Man. Year: 2021)	Chassis No:	LSJE24039MG058198
Colour:	Green	Odometer:	9707 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,052.20	1,659.24	6,392.96	79.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,820.00	1,310.00	3,510.00	72.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>12,872.20</b>	<b>2,969.24</b>	<b>9,902.96</b>	<b>76.93</b>
<b>+ Car Rental (6.0 x S\$90.95/day) (S\$)</b>		545.70		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,516.94</b>		

INSPECTION

Date of Assignment:	05/09/2022	
Date Inspected:	05/09/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	5.0 days	

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FASCIA -FRT BPR (DISC 10%)	Deformed	721.66 F	*649.49 F
2	1		*HEADLAMP ASM -LH (DISC 10%)	Cracked	1,098.86 F	*988.97 F
3	1		*BRACKET -FRT BPR FASCIA -LH (DISC 10%)	Cracked	23.09 F	*20.78 F
4	1		*HEADLAMP ASM -LH	Not Necessary	1,098.86 F	*- F
5	1		*GRILLE ASM -RAD	Not Necessary	978.02 F	*- F
6	1		*BAR ASM -FRT BPR IMP	Not Necessary	624.00 F	*- F
7	1		*PANEL ASM -LEG CTHR	Not Necessary	131.04 F	*- F
8	1		*FINISHER -FRT BPR -LH	Not Necessary	98.80 F	*- F
9	1		*BRACKET -FRT BPR FASCIA -LH	Not Necessary	23.09 F	*- F
10	1		*SUPPORT -FRT BPR FASCIA UPR	Not Necessary	172.33 F	*- F
11	1		*FINISHER -FRT FOG LP CVR -LH	Not Necessary	47.32 F	*- F
12	1		*COVER -FRT FOG LP-LH	Not Necessary	40.25 F	*- F
13	1		*FINISHER -FRT BPR LOWER -LH	Not Necessary	20.38 F	*- F
14	1		*GRILLE -FRT BPR FASCIA LOWER	Not Necessary	149.03 F	*- F
15	1		*BRACKET ASM -HDLP UPP-LH	Not Necessary	22.57 F	*- F
16	1		*BRACKET -F/FDR FRT LWR -LH	Not Necessary	15.80 F	*- F
17	1		*FENDER ASM-FRT -L	Not Necessary	379.81 F	*- F
18	1		*HOOD ASM	Not Necessary	2,407.29 F	*- F

F=Franchise part.

<b>Total Parts (\$\$)</b>	<b>8,052.20</b>	<b>1,659.24</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	1,800.00	350.00
2	SPRAY PAINT	New	2,140.00	660.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
7	TO CHECK & RESET SYSTEM FUNCTION	New	350.00	150.00
8	ISOLATED OF (EV)	New	150.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>4,820.00</b>	<b>1,310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >