



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300693

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 06/02/2023
Reference CC6/CTI22008662/Kpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 3062B
Insured Veh. GBG 3980R
Claim No. SNM22D206261/C02
Policy No. DMCVSNW00095342205
Accident Date 03/09/2022
Inspection Date 06/09/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22008662/Kpa3q2 Date: 06/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBG 3980R	Veh. Inspected	SHA 3062B
	Policy No.	DMCVSNW00095342205	Coverage (\$)	0.00
	Claim No.	SNM22D206261/C02	Excess (\$)	0.00
	Assign From		Assign Date	06/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI IONIQ (A)	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	KMHC851CVLU189566	Colour	LIGHT BLUE
	Odometer	360030 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	2 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	2 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	9 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/09/2022	Inspection Date	06/09/2022
	Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate		
	Repairer	BIFROST AUTO PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3062B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RADIATOR GRILLE NEW MODEL	CRACKED	1,568.60	1,568.60
2	FLAP ASSY ACTIVE AIR UPPER (LH/RH) @\$824.60	CRACKED	1,649.20	1,649.20
1	FRONT NUMBER PLATE GARNISH	DENTED	188.00	188.00
1	FRONT BUMPER COVER	BUCKLED	481.10	481.10
1	FRONT BUMPER TOP COVER	SERVICEABLE	476.30	-
1	FRONT BUMPER SPONGE	CRACKED	186.90	186.90
1	FRONT BUMPER REINFORCEMENT	BENT	1,136.70	1,136.70
2	FRONT BUMPER REINFORCEMENT ABSORBER (LH/RH) @\$186.50	DISTORTED	373.00	373.00
1	FRONT BUMPER TOWING COVER	SERVICEABLE	29.00	-
1	FRONT BUMPER MOULDING CENTRE UPPER	CRACKED	368.50	368.50
1	FRONT BUMPER MOULDING	SERVICEABLE	93.60	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$35.00	TO REPAIR SEE LABOUR	70.00	-
2	FRONT BUMPER BRACKET (LH/RH) @\$28.00	SERVICEABLE	56.00	-
2	FRONT BUMPER RETAINER MOUNTING (LH/RH) @\$65.30	SERVICEABLE	130.60	-
10	FRONT BUMPER CLIPS	NECESSARY	25.00	25.00
1	HEADLAMP SUPPORT PANEL ASSY	CRACKED	1,139.30	1,139.30
2	HEADLAMP (LH/RH) @\$3987.30	CRACKED	7,974.60	4,220.60
1	RADIATOR INVERTER	BENT	884.80	884.80
1	RADIATOR	PUNCTURE	710.50	710.50
1	AIRCON CONDENSER	PUNCTURE	663.60	663.60
1	BOOT LID	BENT	2,549.70	2,549.70
1	BOOT LID RUBBER	DISTORTED	187.40	187.40
1	BOOT LID LOCK UPPER	DENTED	224.00	224.00
1	BOOT LID 'H' EMBLME	NECESSARY	28.00	28.00
1	EMBLEM -HYBRID	NECESSARY	24.30	24.30
1	EMBLEM -LONIQ	NECESSARY	31.30	31.30
2	BOOT LID LAMP (LH/RH) @\$822.00	O/S CUT / N/S CRACKED	1,644.00	1,644.00
1	BOOT LID TRIMBOARD	MTG CRACKED	259.70	259.70
10	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00

Report Ref No. CC6/CTI22008662/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LID TRIMBOARD ,CENTRE	SERVICEABLE	159.60	-
2	BOOT LID TRIMBOARD SIDE (LH/RH) @\$92.50	SERVICEABLE	185.00	-
1	BOOT LID TRIMBOARD REAR	SERVICEABLE	124.80	-
1	BOOT LID GLASS ,LOWER	SHATTERED	584.90	584.90
1	BOOT LID GLASS LOWER MOULDING	NO SUCH PARTS	145.20	-
1	REAR BUMPER	BUCKLED	459.40	459.40
1	REAR BUMPER REINFORCEMENT	BENT	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$188.10	BENT	376.20	376.20
1	ANTENNA ASSY -SMARTK OUTER	MTG CRACKED	689.50	689.50
1	REAR BUMPER CENTRE MOULDING ASSY	CRACKED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	CRACKED	155.00	155.00
1	REAR BUMPER STAY	SERVICEABLE	138.10	-
2	REAR BUMPER SIDE RETAINER (LH/RH) @\$85.80	SERVICEABLE	171.60	-
1	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER CENTRE	CRACKED	123.85	123.85
2	REAR BUMPER SIDE UNDER (LH/RH) @\$123.10	SERVICEABLE	246.20	-
1	REAR BUMPER REAR HOOK	TO REPAIR SEE LABOUR	94.60	-
2	REAR BUMPER REFLECTOR LAMP (LH/RH) @\$82.90	SERVICEABLE	165.80	-
1	REAR BUMPER TOWING COVER	SERVICEABLE	98.80	-
1	REAR BUMPER REVERSE LIGHT (PARKING BRAKE LIGHT)	MTG CRACKED	328.60	328.60
1	LICENCE LAMP	SERVICEABLE	193.53	-
1	LICENCE LAMP WIRE	SERVICEABLE	135.80	-
2	TAIL LAMP (LH/RH) @\$935.40	SERVICEABLE	1,870.80	-
2	TAIL LAMP QUARTER PANEL (LH/RH) @\$208.90	TO REPAIR SEE LABOUR	417.80	-
1	REAR PANEL	BENT	532.00	532.00
1	REAR PANEL GARNISH	DENTED / DISTORTED	346.80	346.80
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	892.50	-
1	SPARE TYRE PANEL UNDER CENTRE PANEL	TO REPAIR SEE LABOUR	338.80	-

Report Ref No. CC6/CTI22008662/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SPARE TYRE PANEL UNDER SIDE PANEL (LH/RH) @ \$239.80	TO REPAIR SEE LABOUR	479.60	-
1	REAR TRAY TOOLS BOX RH	SERVICEABLE	675.30	-
1	REAR TRAY TOOLS BOX LH	SERVICEABLE	693.20	-
1	REAR TRAY LUGGS CENTER	SERVICEABLE	354.20	-
1	EXHAUST SILENCER	TO REPAIR SEE LABOUR	943.50	-
1	EXHAUST PIPE HANGER	SERVICEABLE	29.20	-
1	RADIATOR FAN BLOWER MOTOR ASSY (ADDITIONAL)	CRACKED	1,459.60	1,459.60
1	ELECTRONIC CLUTCH ACTUATOR ASSY (ADDITIONAL)	DENTED / CRACKED	6,345.80	6,345.80
1	REAR SPOILER (ADDITIONAL)	CRACKED	1,265.40	1,265.40
	LESS 20% DISCOUNT		-9,050.75	-6,418.06
			36,202.98	25,672.24
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN) }	CRACKED	25.00	45.00
1	FRONT NO PLATE TRIM COVER (SN) }		30.00	-
1	COOLANT (SN)	NECESSARY	45.00	30.00
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NECESSARY	35.00	35.00
1	BOOT LID COMFORT CABLINK TEL NO.STICKER (SN)	NECESSARY	30.00	30.00
1	REAR NO.PLATE +TRIM COVER (SN)	CRACKED	45.00	45.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR BUMPER REVERSE SENSOR (SN)	DENTED	180.00	180.00
1	SPARE TYRE PANEL TOP COVER SILICON (SN)	NOT NECESSARY	250.00	-
2	CLUTCH FLUID @\$85.00 (50%) (SN) (ADDITIONAL)		170.00	85.00
			856.00	496.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKET TOP (LH/RH) ,REAR BUMPER REAR HOOK,TAIL LAMP QUARTER PANEL (LH/RH),SPARE TYRE PANEL,SPARE TYRE PANEL UNDER CENTRE PANEL,SPARE TYRE PANEL UNDER SIDE PANEL (LH/RH) AND EXHAUST SILENCER .		2,000.00	1,200.00
	SPRAY PAINTING CHARGE .		1,800.00	800.00
	WIRING CHARGE.		100.00	40.00

Report Ref No. CC6/CTI22008662/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.	NOT NECESSARY	100.00	60.00
	TOWING CHARGE.		80.00	50.00
	REMOVE/REFIX REAR WINDSCREEN GLASS .		240.00	180.00
	REMOVE/REFIX REVERSE SENSOR .		120.00	50.00
	REMOVE/REFIX EXHAUST PIPE .		80.00	-
	REMOVE/REFIX RADIATOR .		90.00	50.00
	REMOVE/REFIX AIRCON & REFILL GAS.		130.00	100.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	180.00
			5,290.00	2,710.00
GRAND TOTAL			42,348.98	28,878.24
RECOMMENDED COST OF REPAIR SUM				26,500.00

Report Ref No. CC6/CTI22008662/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 3062B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 3062B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 3062B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 3062B

RE-INSPECTION

